

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | R | A | N | O | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 8 | 7 | 0 | 4 | 1 | 9 | 8 | 10 | 8 | 0 | 15 | 15 | 8 | 10 | 9

02 | During Mode 1 operation, condenser gas sample monitor (2RITS-0645) was
03 | discovered to be inoperable. Grab samples were taken to verify radiation
04 | levels were normal per E.T.S. 2.2.2 monitoring requirement #3. Daily
05 | grab samples were initiated until monitor could be returned to service.
06 | There have been no similar occurrences. Reportable per Enviro. Tech.
07 | Spec. 5.6.2.b.
08 |

09 | M | C | E | B | M | O | I | T | O | R | X | Z | Z | L | NO | 8 | 0 | 0 | 2 | 1 | 0 | 4 | L | NA | C | 5 | 1 | 7

10 | Investigation revealed the sealed outboard bearing on the sample motor
11 | had seized. Pump motor working environment requires sealed bearings.
12 | Both the inboard and outboard sealed bearings were replaced. The unit
13 | was tested and returned to operational status.
14 |

15 | E | 0 | 1 | 1 | 5 | Power Escalation | A | NA

16 | Z | Z | NA | NA | NA

17 | 0 | 0 | 0 | Z | NA

18 | 0 | 0 | 0 | NA

19 | Z | NA

20 | N | NA

POOR ORIGINAL