

### LICENSEE EVENT REPORT

8005190487

CONTROL BLOCK: | | | | | | | | 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

|    |           |    |    |    |    |    |   |    |    |        |              |    |           |
|----|-----------|----|----|----|----|----|---|----|----|--------|--------------|----|-----------|
| 01 | GA EI H 2 | 00 | -  | 00 | 00 | 00 | - | 00 | 03 | 411111 | 4            | 5  |           |
| 7  | 8         | 9  | 14 | 15 |    |    |   |    | 25 | 26     | LICENSE TYPE | 30 | 57 CAT 58 |

|    |   |          |         |               |    |    |            |    |    |             |    |
|----|---|----------|---------|---------------|----|----|------------|----|----|-------------|----|
| 01 | L | 05000366 | 0042280 | 0050780       |    |    |            |    |    |             |    |
| 7  | 8 | 60       | 61      | DOCKET NUMBER | 68 | 69 | EVENT DATE | 74 | 75 | REPORT DATE | 80 |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During an instrument check, the "A" Drywell H<sub>2</sub> - O<sub>2</sub> analyzer was found,  
 03 | giving an erroneous reading. In investigating this problem, it was  
 04 | discovered that the "A" analyzer had a defective cell. The "B" analyzer  
 05 | was operable. There were no effects upon public health and safety due  
 06 | to this event. This is a repetitive event as last reported on Reportable  
 07 | Occurrence Report No. 50-366/1980-065.

|    |   |   |    |    |    |    |    |    |    |    |    |    |
|----|---|---|----|----|----|----|----|----|----|----|----|----|
| 09 | S | A | E  | A  | I  | N  | S  | T  | R  | U  | E  | Z  |
| 7  | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 20 |

|    |    |     |    |    |    |    |    |    |    |    |
|----|----|-----|----|----|----|----|----|----|----|----|
| 17 | 80 | 067 | 03 | L  | 0  |    |    |    |    |    |
| 21 | 22 | 23  | 24 | 26 | 27 | 28 | 29 | 30 | 31 | 32 |

ACTION TAKEN: L Z | FUTURE ACTION: Z | EFFECT ON PLANT: Z | SHUTDOWN METHOD: Z | HOURS: 0000 | ATTACHMENT SUBMITTED: Y | NRPD-4 FORM SUB: N | PRIME COMP. SUPPLIER: N | COMPONENT MANUFACTURER: X999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause has been attributed to a defective cell. The cell was replaced.  
 11 | The analyzer was recalibrated and placed into service. This instrument,  
 12 | Model K-4, is manufactured by Comsip Delphi.

|    |   |      |    |    |                       |
|----|---|------|----|----|-----------------------|
| 15 | C | 0111 | NA | B  | Operator observation. |
| 7  | 8 | 9    | 12 | 13 | 44                    |

|    |   |   |    |    |
|----|---|---|----|----|
| 16 | Z | Z | NA | NA |
| 7  | 8 | 9 | 10 | 11 |

|    |     |   |    |
|----|-----|---|----|
| 17 | 000 | Z | NA |
| 7  | 8   | 9 | 11 |

|    |     |    |
|----|-----|----|
| 18 | 000 | NA |
| 7  | 8   | 9  |

|    |   |    |
|----|---|----|
| 19 | Z | NA |
| 7  | 8 | 9  |

|    |   |    |
|----|---|----|
| 20 | N | NA |
| 7  | 8 | 9  |

**POOR ORIGINAL**

NRC USE ONLY

98017-128

## NARRATIVE REPORT

Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-366/1980-067.

While doing an instrument check, the "A" Drywell H<sub>2</sub> - O<sub>2</sub> analyzer was found giving an erroneous reading. While investigating this problem, it was discovered that the "A" analyzer had a defective cell. The "B" analyzer was operable. There were no effects upon public health and safety due to this event. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-366/1980-065.

The defective cell was replaced. The analyzer was recalibrated and placed into service. This instrument, Model K-4, is manufactured by Comsip Delphi.

The reactor was in the run mode at 280 Mwt. The operation of the plant was not affected. Unit II is the only unit that utilizes this type of analyzer. This instrument failure does not indicate that there is any generic problem with this instrument.