



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TIC

APR 30 1980

State of Illinois
Department of Public Health
ATTN: Mr. Gary N. Wright, Chief
Division of Nuclear Safety
535 West Jefferson Street
Springfield, IL 62761

Gentlemen:

The attached IE Circular No. 80-09 titled "Problems With Plant Internal Communications Systems" was sent to the licensees listed below on April 28, 1980 for action:

American Electric Power Service Corporation
Indiana and Michigan Power Company
D. C. Cook 1, 2 (50-315, 50-316)

Cincinnati Gas & Electric Company
Zimmer (50-358)

Cleveland Electric Illuminating Company
Perry 1, 2 (50-440, 50-441)

Commonwealth Edison Company
Braidwood 1, 2 (50-456, 50-457)
Byron 1, 2 (50-454, 50-455)
Dresden 1, 2, 3 (50-10, 50-237, 50-249)
LaSalle 1, 2 (50-373, 50-374)
Quad-Cities 1, 2 (50-254, 50-265)
Zion 1, 2 (50-295, 50-304)

Consumers Power Company
Big Rock Point (50-155)
Midland 1, 2 (50-329, 50-330)
Palisades (50-255)

Dairyland Power Cooperative
LACBWR (50-409)

Detroit Edison Company
Fermi 2 (50-341)

Illinois Power Company
Clinton 1, 2 (50-461, 50-462)

8 0 0 5 2 1 0 6 2 3

APR 10 1980

Iowa Electric Light & Power Company
Duane Arnold (50-331)

Northern Indiana Public Service Company
Bailly (50-367)

Northern States Power Company
Monticello (50-263)
Prairie Island 1, 2 (50-282, 50-306)

Public Service of Indiana
Marble Hill 1, 2 (50-546, 50-547)

Toledo Edison Company
Davis-Besse 1 (50-346)

Union Electric Company
Callaway 1, 2 (50-483, 50-486)

Wisconsin Electric Power Company
Point Beach 1, 2 (50-266, 50-301)

Wisconsin Public Service Corporation
Kewaunee (50-305)

Sincerely,



Helen Pappas, Chief
Administrative Branch

Enclosure: IE Circular
No. 80-09

cc w/encl:
Mr. D. W. Kane,
Sargent & Lundy
Central Files
Reproduction Unit NRC 20b
Local PDR
NSIC
TIC

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

April 28, 1980

SSINS No.: 6830
Accession No.:
8002280663

DUPLICATE

IE Circular No. 80-09

PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS

Description of Circumstances at the Kewaunee Power Plant:

On January 17, 1980, the Kewaunee Nuclear Power Plant lost offsite power to its 4160V non-safeguards buses. Since the system used for internal communications, paging and evacuation alarm purposes (Gai-tronics) was powered from a non-safeguards bus, plant communications were degraded during the outage. This degraded condition persisted until power was restored to the affected bus thru an emergency safeguards bus. While in the degraded mode, the licensee used two-way portable radios for internal communications. The radios performed satisfactorily, per se; however, when transmitting in the vicinity of certain electronic equipment, they induced false signals into the electronic equipment.

Description of Circumstances at the Davis-Besse Power Station:

On October 15, 1979, the Davis-Besse Power Station lost all offsite power. During the period when offsite power was not available, the licensee noted that the internal three digit telephones (GTE) would not function. In addition, the NRC "Red Phone" was subsequently reported to have been out of service. Other licensee phone systems (Gai-tronics and the outside four digit Ohio Bell phones) did work.

Following this event, the licensee provided emergency power to its phones and the NRC took action through AT&T to provide emergency power to all Red Phones. (Note: Although the communications system at Davis-Besse was not designed to meet the single failure criterion, its FSAR states that the main internal communications system is supplied by two redundant power feeders from the uninterruptable instrumentation distribution panels.)

RECOMMENDED ACTION FOR LICENSEES AND HOLDERS OF CONSTRUCTION PERMITS

All licensees of nuclear power reactors and holders of construction permits should be aware of the potential problems described above. Because of the generic implications of the above problems, it is recommended that the following actions be considered:

1. Determine the source of power for plant internal communications systems;
2. Upgrade the internal communications systems to assure operability during the loss of offsite power or other foreseeable events;

3. Determine whether any plant electronic equipment may be adversely affected by portable radio transmissions. This determination should include, but not be limited to, the computer system, electro-hydraulic system, and nuclear instrumentation system; and
4. Instruct employees on the use of radios in areas susceptible to electromagnetic interference.

No written response to this Circular is required; however, if additional information regarding these matters is required, contact the Director of the appropriate NRC Regional Office.

IE Circular No. 80-09
April 28, 1980

Enclosure

RECENTLY ISSUED
IE CIRCULARS

| Circular No. | Subject | Date of Issue | Issued to |
|--------------|---|---------------|--|
| 80-08 | BWR Technical Specification Inconsistency - RPS Response Time | 4/18/80 | All General Electric BWR's holding a power reactor OL |
| 80-07 | Problems with HPCI Turbine Oil System | 4/3/80 | All holders of a power reactor OL or CP |
| 80-06 | Control and Accountability Systems for Implant Therapy Sources | 4/14/80 | Medical licensees in Categories G and G1 |
| 80-05 | Emergency Diesel-Generator Lubricating Oil Addition and Onsite Supply | 4/1/80 | All holders of a power reactor OL or CP |
| 80-04 | Securing of Threaded Locking Devices on Safety-Related Equipment | 3/14/80 | All holders of a power reactor OL or CP |
| 80-03 | Protection from Toxic Gas Hazards | 3/6/80 | All holders of a power reactor OL |
| 80-02 | Nuclear Power Plant Staff Work Hours | 2/1/80 | All holders of Reactor OLs, including research and test reactors, and CPs |
| 80-01 | Service Advice for GE Induction Disc Relays | 1/17/80 | All licensees of nuclear power reactor operating facilities and holders of nuclear power reactor CPs |
| 79-25 | Shock Arrestor Strut Assembly Interference | 12/20/79 | All licensees and holders of power reactor CPs |
| 79-24 | Proper Installation and Calibration of Core Spray Pipe Break Detection Equipment on BWRs. | 11/26/79 | All Holders of a Power Reactor OL or CP |