

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C R E P 1 2000-00000000-000 3411111 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T
01 L 6050-0325 7042480 8051980 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing PT 3.1.7PC, Reactor Low Water No. 2 and 3 Channel Calibration and
03 Functional Check, low level switch 1-B21-LITS-N031A-2 failed to actuate. The report-
04 able limit for this switch is >194.63" water applied. Also, low pressure switch 1-B21-
05 LITS-N031B-3 actuated at 121.1" water applied while the reportable limit is >117.18"
06 water applied. The health and safety of the public were not affected by this event.
07 Technical Specifications 3.3.3, 6.9.1.9a

08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
I B E E I N S T R U S Z
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 0 0 4 5 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E C Z Z 0 0 0 0 Y Y N Y 0 1 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Both switch failures were attributed to instrument drift. Both were recalibrated and
11 returned to service satisfactorily. Due to a history of drift problems, they will be
12 replaced with analog type instrumentation during a future outage.
13
14

15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 0 8 7 NA B Periodic Test
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA

20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PUBLICITY ISSUED DESCRIPTION
N NA
NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521

8005280655

LER ATTACHMENT - RO # 1-80-45

Facility: BSEP Unit No. 1

Event Date: 4-24-80

The I&C Technicians also found a loose locking screw that holds switch 2 of 1-B21-LITS-N031A in place. The loose screw could have allowed possible bumping and moving of the switch such that it would not actuate. Locking screws on both instruments were checked for tightness at the time and are presently checked quarterly.