

LICENSEE EVENT REPORT

UPDATE REPORT: PREVIOUS REPORT DATE 7-31-79

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C B E P 2 00-000000-000 411111 5

01 REPORT SOURCE L 050-0324 0702179 8051280 9

02 While performing PT 1.1.4PC, Reactor Low Water Level #1 Channel Calibration,
03 B21-LIS-N017C, switch 1 was found to be out of tolerance low. The required
04 value is >= 12.5 inches of water and the "as found" value was 7.07 inches of
05 water.
06
07
08 Technical Specifications 2.2.1, 6.9.1.9a

09 SYSTEM CODE I A CAUSE CODE X CAUSE SUBCODE Z COMPONENT CODE INSTRU COMP. SUBCODE E VALVE SUBCODE Z
LER/RO REPORT NUMBER 7 9 EVENT YEAR 7 9 SEQUENTIAL REPORT NO. 0 5 4 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 1
ACTION TAKEN E FUTURE ACTION X EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0 0 0 0 ATTACHMENT SUBMITTED Y NPRD-4 FORM SUB. Y PRIME COMP. SUPPLIER N COMPONENT MANUFACTURER B 0 8 0

10 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
11 The only reason determined was instrument drift. The instrument was recalibrated
12 and returned to service. A plant modification has been written to replace the
13 bi-stable switches with analog instrumentation during a future outage. This new
14 instrumentation is much more stable and should greatly reduce the drift problems
15 now being encountered.

15 FACILITY STATUS G % POWER 0 0 0 OTHER STATUS N/A METHOD OF DISCOVERY B DISCOVERY DESCRIPTION Periodic Test

16 ACTIVITY CONTENT Z RELEASED OF RELEASE Z AMOUNT OF ACTIVITY N/A LOCATION OF RELEASE N/A

17 PERSONNEL EXPOSURES NUMBER 0 0 0 TYPE Z DESCRIPTION N/A

18 PERSONNEL INJURIES NUMBER 0 0 0 DESCRIPTION N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION N/A

20 PUBLICITY ISSUED N DESCRIPTION N/A 8005280 670

LER ATTACHMENT - RO NO. 2-79-054

Facility: BSEP Unit No. 2

Event Date: July 2, 1979

During the 1980 Unit No. 2 refueling outage, several instruments were scheduled to be replaced with more reliable analog-type instrumentation. Prior to the refueling outage, Carolina Power & Light Company contacted other utilities which had already made this conversion to learn of any problems they experienced. From these conversations, it was decided that a thorough bench-testing program should be implemented before actual installation. During this bench testing, several problems were identified which we feel make these instruments unsuitable for operation at this time. Upon completion of correcting these problems and thorough testing, this new analog instrumentation will be installed.