


## LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	L	I	B	P	1	2	0	0	0	0	0	0	0	3	0	4	1	1	1	1	4	5
7	8	9	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	31	CAT	38	5								

CONT

0 1	R	E	P	0	6	0	1	5	15	7	0	14	12	3	18	10	8	0	5	12	3	8	0	9	
7	8	REPORT SOURCE	60	61	DOCKET NUMBER	62	63	EVENT DATE	74	75	REPORT DATE	80													

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

- 0 2 Following intermittent automatic test circuit alarms, the sensor channel
- 0 3 ID of the Reactor Depressurizing System was removed from service to correct
- 0 4 the problem. All four blowdown loops remained operable under this condition
- 0 5 with 2/3 logic instead of 2/4. No hazard occurred and the equipment was
- 0 6 restored to operable status in less than four hours. Similar to R0-80-08.
- 0 7 Reportability is based on Tech Specs 6.9.2.b(2).

0 8	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
-----	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

5 9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE	REVISION NO.																																			
6 H	X	Z	Z Z Z Z	Z	Z																																				
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	COMPONENT MANUFACTURER																																				
8 0	0 1 0	10 13	L	0	Z 9 9 9																																				
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER																																	
X 18	Z 19	Z 20	Z 21	0 1 0	0 0	N 23	N 24	Z 25																																	

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- 1 0 Setpoint drift in the conservative direction on reactor level transmitter
- 1 1 LT-3183 caused the alarm. The unit was readjusted by venting and rezeroing
- 1 2 the transmitter. Removal of the equipment from service is allowed per
- 1 3 Tech Spec 11.3.1.5-3. Investigation of the cause of drift is planned during
- 1 4 a future outage.

1 5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION																																									
E	10 8 17	N/A	A	Operator Observation																																									
ACTIVITY CONTENT	RELEASED OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE																																										
Z	Z	Z	NA																																										

1 6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION																																									
Z	0 0 0	Z	NA																																									

1 7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
PERSONNEL INJURIES	NUMBER	DESCRIPTION																																									
Z	0 0 0	NA																																									

1 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
LOSS OF OR DAMAGE TO FACILITY	TYPE	DESCRIPTION																																								
Z	NA																																									

1 9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
PUBLICITY	ISSUED	DESCRIPTION																																							
Z	N	NA																																							

68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

8005280745