

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] T N S N P 1 1 [000] - [000] [000] [000] [000] [000] [411111] [] [] [] (5)
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JJ 27 LMT 56

CONT
[01] REPORT SOURCE L G [050] [003] [27] [015] [158] [010] [052] [88] [0] [0] (9)
7 8 9 10 11 SOCKET NUMBER 12 13 14 15 16 17 18 19 20 21 REPORT DATE 22

[02] EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[02] At 0100 CDST with Unit 1 in Mode 3, it was discovered that the test switches
[03] on the containment purge exhaust radiation monitors were in the test positib
[04] making the monitors inoperable (TS LCO 3.3.3.1 requires one monitor
[05] operable in all modes) making them unable to provide a containment vent
[06] isolation signal. Since Unit 1 had not yet achieved initial criticality
[07] there were no radiation releases. Therefore there was no danger to the
[08] health and safety of the public.
7 8 9

[03] SYSTEM CODE M C (11) CAUSE CODE A (12) CAUSE SUBCODE A (13) COMPONENT CODE I N S T R U (14) COMP SUBCODE E (15) VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 14 15 16 17 18 19 20
[17] LED NO REPORT NUMBER 8 0 (17) EVENT YEAR 8 0 (21) SEQUENTIAL REPORT NO. 0 4 8 (24) OCCURRENCE CODE 0 1 (28) REPORT TYPE T (30) REVISION NO. 0 (32)
ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
[X] (33) [Z] (34) [Z] (35) [Z] (36) [0000] (37) [Y] (40) [N] (42) [Z] (43) [Z] 999 (44)

[03] CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[10] Operator error in placing both trains of radiation monitors in test at the
[11] same time. Upon discovery the radiation monitors were immediately re-
[12] turned operable.

[13] _____
7 8 9

[15] FACILITY STATUS B (20) % POWER 0 0 0 (25) OTHER STATUS N/A (30) METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION Operator observation (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[16] RELEASED OR RELEASE ACTIVITY CONTENT Z Z (22) AMOUNT OF ACTIVITY N/A (35) LOCATION OF RELEASE N/A (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[17] PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION N/A (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[18] PERSONNEL INJURIES NUMBER 0 0 (40) DESCRIPTION N/A (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[19] LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION N/A (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[20] PUBLICITY TYPE Z (44) DESCRIPTION N/A (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARED BY Gary W. Gault PHONE: (615) 842-0295

8006060403

POOR ORIGINAL

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/ 8048 Technical Specification Involved 3.3.3.1

Reported Under Technical Specification Section 6.9.1.12.i

Date of Occurrence 5/15/80 Time of Occurrence: 0100 CDST Unit 1

Identification and Description of Occurrence

Containment purge air exhaust monitors test switches were discovered to be in the test position making the monitors inoperable. LCO 3.3.3.1 requires at least one monitor be operable. Action 26 of the LCO requiring closure of penetrations which provide direct access from the containment atmosphere to the outside atmosphere was not met. The inoperable containment purge air exhaust radiation monitors would not have provided a containment ventilation isolation signal, however, isolation was still functional from containment upper and lower radiation monitors and safety injection signals.

Conditions Prior to Occurrence

Unit 1 in Mode 3. Preoperational Testing

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment.

N/A

Apparent Cause of Occurrence

Personnel error.

Analysis of Occurrence

There was no hazard to the public health and safety.

Corrective Action

Monitors were immediately removed from test mode upon discovery. Administrative Instruction (AI-5) system status checklist was revised to require that each oncoming shift verify that the test switches are in the off position.

Failure Data

N/A