

Foxboro, MA U.S.A. 02035-2099

Telephone 508-543-8750

Telex 927-602 or TRT 174090

**The Foxboro Company**

November 3, 1989

Mr. Kamalakar R. Naidu  
 United States Nuclear Regulatory Commission  
 Dept. 9D4  
 Washington, DC 20555

Dear Mr. Naidu:


As discussed in our telephone conversation of October 31, 1989, we have become aware of a potential problem related to the application of the model N-2AO-L2C-R, logic to contact output module, in certain configurations. When applied in a particular manner the model N-2AO-L2C-R may not de-energize when the actuator that drives the model N-2AO-L2C-R suffers a loss of power.

Preliminary testing, performed this past week, indicates that this situation may occur under certain limited applications. If two model N-2AO-L2C-R modules are actuated by a single actuator, and the two model N-2AO-L2C-R modules are mounted in two separate nests, or cardframes, and one on the model N-2AO-L2C-R is mounted in the same nest as the actuator, and the actuator nest loses its +15 VDC power source, the model N-2AO-L2C-R in the nest that remains powered may not de-energize. In some cases, the user may assume that the model N-2AO-L2C-R module de-energizes on loss of power to the actuator module as part of his design.

We feel that the likelihood of occurrence is very low since thousands of model N-2AO-L2C-R modules have been applied, over 2000 in nuclear plants, without a single report of such an occurrence. It should also be noted that loss of power to a nest would, under most circumstances, be detected by the user either directly, via contact on the power distribution module, or indirectly by de-energization of the model N-2AO-L2C-R module in the affected nest. Nonetheless, Foxboro intends to perform a series of tests on the model N-2AO-L2C-R module as well as other relay modules and actuator modules to determine the extent of the potential problem. Once this testing is complete we will notify all customers who have used these modules in nuclear applications. We will also recommend corrective action that will be determined as part of the testing program. For technical questions please contact Mr. James Keiper (1-508-549-6332).

We will keep you informed as the testing progresses.

Very truly yours,



S. Hasan Rizvi, D100/N04-2B  
 Manager, Corporate Quality Assurance

baa(PW016989)

IEL9  
~~IK09~~

110



8911090341 891103  
 PDR PT21 EMVFOXB  
 89 PNU

ocket Control

Please process

RIDS Code IE:09

Thanks

20961 Katabe