




HELPING BUILD ARKANSAS

ARKANSAS POWER & LIGHT COMPANY

9TH & LOUISIANA STREETS • LITTLE ROCK, ARKANSAS 72203 • (501) 372-4311

September 17, 1976

Mr. E. Morris Howard, Director
 Office of Inspection & Enforcement
 Region IV
 U. S. Nuclear Regulatory Commission
 611 Ryan Plaza Drive, Suite 1000
 Arlington, Texas 76012



Subject: Arkansas Power & Light Company
 Arkansas Nuclear One-Unit 1
 Docket No. 50-313
 License No. DPR-51
 Reportable Occurrence Report
No. 50-313/76-23

Gentlemen:

In accordance with Technical Specification 6.12.3.2 we have attached the subject report concerning our failure to comply with the surveillance test schedule.

Very truly yours,

Donald A. Rueter
 Manager, Licensing

DAR:DGM:ay

Attachment

cc: Mr. W. D. MacDonald, Director
 Office of Management Information
 and Program Control
 U. S. Nuclear Regulatory Commission
 Washington, D. C. 20555

COPY SENT REGION IV

Mr. E. Volgenau, Director
 Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 Washington, D. C. 20555

~~9802~~

8004180593 3



1. Reportable Occurrence Report No. 50-313/76-23
2. Report Date: September 20, 1976 3. Occurrence Date: August 23, 1976
4. Facility: Arkansas Nuclear One-Unit 1
 Russellville, Arkansas

5. Identification of Occurrence:
 Failure to comply with surveillance test schedule.

6. Conditions Prior to Occurrence:

Steady-State Power _____	Reactor Power <u> 0 </u> MWth
Hot Standby _____	Net Output <u> 0 </u> MWe
Cold Shutdown <u> X </u>	Percent of Full Power <u> 0 </u> %
Refueling Shutdown _____	Load Changes During Routine Power Operation _____
Routine Startup Operation _____	
Routine Shutdown Operation _____	
Other (specify)	

7. Description of Occurrence:

On August 23, 1976, during the review of surveillance test, it was found that the following tests were not conducted at the required surveillance interval.

1. Offsite power protective relaying interlocks and circuitry weekly test scheduled for 1/30/76 and 2/13/76 were conducted on 2/4/76 and 2/10/76. The test scheduled for 7/2/76 was not conducted. The weekly test also had not been conducted prior to criticality on 1/18/76, 6/19/76 and 6/28/76.

7. Description of Occurrence: (continued)

2. Diesel Generator protective relaying, starting interlocks and circuitry monthly test scheduled for 1/23/76, 2/20/76 and 3/19/76 were conducted on 2/4/76, 2/10/76 and 3/4/76. Also, a monthly test had not been conducted prior to criticality on 6/19/76 and 6/28/75.
3. Station batteries and switchyard batteries quarterly tests were not conducted prior to heat up above 200F on 6/19/76 and 6/28/76.

8. Designation of Apparent Cause of Occurrence:

Design	_____	Procedure	_____
Manufacture	_____	Unusual Service Condition Including Environmental	_____
Installation/ Construction	_____	Component Failure	_____
Operator	_____		
Other (specify)	X		

Failure of the individual responsible for these tests to recognize the technical specification requirements.

9. Analysis of Occurrence:

Surveillance tests have been satisfactorily completed since these occurrences thus there was no hazard to the health and safety of the public.

10. Corrective Action:

The occurrences and the technical specification requirements have been discussed in detail with the individual responsible for the surveillance test implementation.

11. Failure Data:

Similar Reports:

76-02 - The pilot cell voltage readings for station batteries were not taken

76-19 - Failure to perform surveillance test on Control Room emergency ventilation system at the required frequency

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: ARARKI LICENSE NUMBER: 00-000000-00 LICENSE TYPE: 411111 EVENT TYPE: 03

REPORT TYPE: L REPORT SOURCE: L DOCKET NUMBER: 050-0313 EVENT DATE: 082376 REPORT DATE: 092076

EVENT DESCRIPTION

02 DURING GOLD SHUTDOWN, FAILURES TO COMPLY WITH SURVEILLANCE TEST SCHEDULES WERE FOUND. THESE INCLUDE OFFSITE POWER PROTECTIVE RELAYS AND INTERLOCKS WEEKLY TEST, DIESEL GENERATOR PROTECTIVE RELAYS AND INTERLOCKS WEEKLY TEST, AND STATION BATTERIES AND SWITCHYARD BATTERIES QUARTERLY TEST. WHILE SURVEILLANCE TESTS HAVE BEEN SATISFACTORILY COMPLETED. (58-313/76-23)

SYSTEM CODE: ZZ CAUSE CODE: A COMPONENT CODE: ZZZZZZ PRIME COMPONENT SUPPLIER: Z COMPONENT MANUFACTURER: ZZZZ VIOLATION: Y

CAUSE DESCRIPTION

08 THE INDIVIDUAL RESPONSIBLE FOR THESE TESTS FAILED TO RECOGNIZE THE TECHNICAL SPECIFICATION REQUIREMENTS. THE INDIVIDUAL WAS INFORMED OF HIS RESPONSIBILITY FOR THE SURVEILLANCE TESTS IMPLEMENTATION.

FACILITY STATUS: G % POWER: 000 OTHER STATUS: NA METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: NA

FORM OF ACTIVITY RELEASED: Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000 DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

19 NA

NAME: DAVID G. MARDIS PHONE: (501) 371-4496