

# LICENSEE EVENT REPORT

CONTROL BLD

--	--	--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME

LICENSE NUMBER

LICENSE TYPE

EVENT TYPE

01	A	R	A	R	K	I	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9	14	15	25	26	30	31	32															

01	CONT		L	L	0	5	0	-	0	3	1	3	0	5	1	2	7	6	0	6	0	9	7	6
7	8	57	58	59	60	61	68	69	74	75	80													

## EVENT DESCRIPTION

02 | During the refueling period E.S. test, four valves and  
03 | a Reactor Building cooling fan failed to properly respond to  
04 | their respective E.S. signals. Redundant components were  
05 | available and operable. No previous similar occurrence. Following  
06 | adjustments and replacements all components were successfully reset.

07	S	H	E	V	A	L	V	E	X	N	Z	9	9	9	N
7	8	9	10	11	12	13	17	43	44	47	48				

## CAUSE DESCRIPTION

08 | Two valves torqued out due to aging caused friction between  
09 | stem and packing. One valve had dirty relay contact. One valve had  
10 | loose connection at terminal plug. Contact in fan handswitch failed.

11	H	0	0	0	NA	b	NA		
7	8	9	10	12	13	44	45	46	80

  

12	Z	Z	NA	NA			
7	8	9	10	11	44	45	80

## PERSONNEL EXPOSURES

13	0	0	0	Z	NA		
7	8	9	10	11	12	13	80

## PERSONNEL INJURIES

14	0	0	0	NA		
7	8	9	10	11	12	80

## OFFSITE CONSEQUENCES

15	NA		
7	8	9	80

## LOSS OR DAMAGE TO FACILITY

16	Z	NA		
7	8	9	10	80

## PUBLICITY

17	NA		
7	8	9	80

## ADDITIONAL FACTORS

18 | See text of report for individual component manufacturer  
19 | nameplate data.

NAME Dan Williams

PHONE (501)371-4192

8004180717

1. Reportable Occurrence Report No. 50-313/76-9
2. Report Date: June 9, 1976      3. Occurrence Date: May 12, 1976

4. Facility:      Arkansas Nuclear One-Unit 1  
                          Russellville, Arkansas

5. Identification of Occurrence:

Failure to respond to simulated E.S. signal during refueling period testing.

6. Conditions Prior to Occurrence:

Steady-State Power _____	Reactor Power _____ 0 _____ MWh
Hot Standby _____	Net Output _____ 0 _____ MWe
Cold Shutdown _____	Percent of Full Power _____ 0 _____ %
Refueling Shutdown _____ X _____	Load Changes During Routine Power Operation _____
Routine Startup Operation _____	
Routine Shutdown Operation _____	
Other (specify)      Defueled	

7. Description of Occurrence:

The following equipment failed to respond properly to a simulated E.S. signal during the refueling period test:

- A. Make up pump recirculation valve, CV-1300, which received an E.S. signal but the valve torqued out and did not close.
- B. Auxiliary cooling water valve, CV-3643, which received an E.S. signal but the valve torqued out and did not close.
- C. Service water to the Reactor Building, CV-3814, failed to respond to an E.S. signal and open.
- D. Reactor Building particulate monitor isolation valve, CV-7454, failed to respond to an E.S. signal and close.
- E. Reactor Building cooling fan, VSF-1B failed to start on an E.S. signal.

8. Designation of Apparent Cause of Occurrence:

Design	_____	Procedure	_____
Manufacture	_____	Unusual Service Condition Including Environmental	_____
Installation/ Construction	<u>  X  </u>	Component Failure	<u>  X  </u>
Operator	_____		
Other (specify)	<u>  X  </u>		

See attachment.

9. Analysis of Occurrence:

The redundant component for CV-1300, CV-3643, CV-3814, CV-7454 and VSF-1B was operable and did respond properly to an E.S. signal. CV-3814, CV-7454 and VSF-1B were also operable manually from the control room. Due to the redundant components responding properly there was no hazard to the health and safety of the public.

10. Corrective Action:

Adjustments were made to the torque switches for CV-1300 and CV-3643 relay was cleaned that caused CV-3814 failure to respond. The loose connection at the terminal plug for CV-7454 was tightened. The hand switch, HS-7411, for VSF-1B was replaced. All components were retested by simulating an E.S. signal and responded properly.

11. Failure Data:

Handswitch HS-7411 is a GE Type CR2940 spring return to neutral.  
CV-1300 is a 2" Bolted Bonnet Gate Valve 1500# Velan Fig. No. W8-354B-13MS  
CV-3643 is an 18" 150# 9123 Double R/L Fisher Controls Butterfly Valve  
ES relay for CV-3814 is GE catalog No. 12HGA11J52

8. Other

- A. The apparent cause for CV-1300 and CV-3643 torquing out was increased friction between the valve stem and packing due to aging.
- B. CV-3814 did not respond due to a dirty relay contact.
- C. CV-7454 did not respond due to a loose connection at a terminal plug.
- D. VSF-1B did not respond due to contact failure in the fan handswitch (HS-7411).