DISTRIBUTION AFTER ISSUANCE OF OPERATING LICENSE U.S. NUCLEAR REGULATORY COM- 1810 1 DOCKET NUMBER 50 - 3/3 NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL FROM: DATE OF DOCUMENT 08/24/77 Mr. E. Morris Howard Little Rock, Arkansas 72203 DATE RECEIVED Donald A. Rueter 09/15/77 NUMBER OF COPIES RECEIVED ZORIGINAL DODY NOTORIZED PROP INPUT FORM BUNCLASSIFIED DESCRIPTION Consists of Tendon Surveillance ENCLOSURE interim Report...Furnishing information on tendon wire tested for tensil strength... THIS DOCUMENT CONTAINS 2p POOR QUALITY PAGES PLANT NAME: ARKANSAS UNIT # 1 jcm 09/16/77 FOR ACTION/INFORMATION SAFET Louis BRANCH CHIEF: (7) INTERNAL DISTRIBUTION HANAUER CHECK EISENHUT SHAO BUTLER GRIMES J. COLLINS PDR: RUSS & LEVIL & A.K.
IC
I'SIC
13 CYS ACRS SENT CATEGORY CONTROL NUMBER



## HELPING BUILD ARKANSAS

## ARKANSAS POWER & LIGHT COMPANY

PO BOX 561 LITTLE ROCK, ARKANSAS 72203 - (501) 371 -4000

August 24, 1977

1-087-6

Mr. E. Morris Howard, Director Office of Inspection & Enforcement Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

> Subject: Arkansas Nuclear One-Unit 1

Docket No. 50-313 License No. DPR-51 Tendon Surveillance Report

File: 0520.2

Gent men:

Pursuant to Arkansas Nuclear One-Unit 1 Technical Specification 6.12.4, we are submitting the following information concerning the subject report.

As required, one tendon wire from each of the three tendon families (dome, vertical and loop) was tested for tensile strength. The tensile strength for two of the three samples taken from a wire in hoop tendon 32H14 fell below the required minimum tensile strength of 240 ksi. A fourth sample was taken from the same wire and tested. The results were also below the minimum tensile strength. The highest tensile strength recorded for these tests was 246 ksi and the lowest value recorded was 229 ksi. These four tests were done on May 24 and 25 1977 using 100 inch sample. tests were done on May 24 and 25, 1977, using 100-inch samples in accordance with Section 7.3 of Operating Procedure 1304.91.

At this time, a total of 46 hoop tendons have been identified as having the same heat of material as tendon 32H14. An engineering evaluation is in progress to determine if this decrease in tensile strength constitutes abnormal degradation of the primary containment.

Therefore, we now submit this interim report on Tendon Surveillance and



Mr. E. Morris Howard - 2 -August 24, 1977 propose to submit a final report no later than November 1, 1977. Very truly yours, Donald A. Rueter Manager, Licensing DAR:DGM:aw