

August 2, 1973

Distribution
OGC
Massar
Shapar
Engelhardt
Pink
Green
REG Central
PDR
LPDR
S. MacKay
F. Miraglia
H. Thornburg

Myron M. Cherry, Esq.
Jenner and Block
One IBM Plaza
Chicago, Illinois 60603

In the Matter of Consumers Power Company
(Midland Plant, Units 1 and 2)
Docket Nos. 50-329 and 50-330

Dear Mr. Cherry:

Pursuant to your letter of July 3, 1973, I am enclosing copies of the (1) inspection plan, (2) field notes and (3) draft of the report relating to the inspection of June 26 - 28, 1973.

This will also confirm my telephone advice to you late yesterday afternoon, that further consideration is being given to those items of your request which are not answered by the enclosures, and that, within the next few days, you will receive what further response we believe we may appropriately make to your unanswered requests.

Sincerely,

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

William Massar
Assist. Chief Hearing Counsel
for AEC Regulatory Staff

Enclosure:
As stated above

cc w/enclosure:

Mr. Alan S. Rosenthal
Dr. John H. Buck
William C. Parler, Esq.
Howard J. Vogel, Esq.
Arthur W. Murphy, Esq.
Dr. David B. Hall
Dr. Clark Goodman
Harold Reis, Esq.
Irving Like, Esq.
Harold P. Graves, Esq.
Milton R. Wessel, Esq.

Ms. Mary Sinclair
Honorable William H. Ward
William J. Ginster, Esq.
James A. Kendall, Esq.
David Comey, Esq.
Honorable Vern Miller
Richard G. Smith, Esq.
Atomic Safety and Licensing
Board Panel
Atomic Safety and Licensing
Appeal Board

Mr. James N. O'Connor

Mr. Frank W. Karas

OFFICE ▶

OGC

SURNAME ▶

8006110433

Massar: djt

8/2/73

LB

Call Hills 1405 9th

(517) 788-1744

Call (W...)
re construction
(...)

AK

FORM CD-1 (1-12-73)

U. S. ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS

REGION III

Construction Inspection Plan (WORK COPY)

✓
1774?
✓
10/22/73
ind...
ind...
ind...

Licensee: Consumers Power Company
50-379/73-05
50-330/73-05

License No. 2000-81 & 82
Category: 1

Facility Name: Midland Plant - Units 1 & 2

Location: Midland, Michigan

PSAK
2:45:30
OK OK OK OK

Type of Licensee: PLR (B & W) - (662 Mwe (each unit))

Type of Inspection: Special Inspection
(Restart of Construction)

Date(s) of Inspection: June 25-28, 1973

Date(s) of Previous Inspection: April 17, 1973

Principal Inspector: P. A. Pahrbarber

6-21-73
(Date)

Accompanying Inspector(s): M. Erb

(Date)

Other Accompanying Personnel: None

(Date)

Reviewed By: D.W. Hayes SPI 213

6/22/73
(Date)

1:6:50
2:5:18

8000
2000
1300
2
NET
555 H-2
506 H-1
1301

6:00
3:45:30

Eff. License ✓
Violation coding 114 ✓

SUMMARY OF FINDINGS

Enforcement Action

A. Violations

None found during inspection - RAR

Sam Miller
1/10/73
114

B. Safety Matters

None of signif. found during insp. - RAR

1/10/73
114

Licensee Action on Previously Identified Enforcement Matters

NA - none held over

INSPECTOR *KCK*

SUMMARY OF PROBLEM

SUMMARY OF INSPECTION RESULTS

INSPECTOR _____

SUMMARY OF PROBLEM

SUMMARY OF INSPECTION RESULTS

550 - 650

Design Changes

None

Unusual Occurrences



RPV } See RO: III
SG } Vendor Insp. Report
Boiler }

Other Significant Findings

Earthquake → Cause No

A. Current Findings

Eng. % 30-35%

Estimate of % construction completed (at date of const.)

Overall: ——— 1-2%

Concrete: ———

Estimate of construction complete in outside

Status of restoration of batch plant

Status of SAR:

Principal Valve Locations:

- 5 -

Principal Pipe Locations:

Rechtel installation (S.W. - to control tank)
Champion temp.

Kellogg ←

Batch Plant - Restoration in progress - almost done (99%)

" " - Lab - to be rebuilt (Pittsburgh - temp.)

B. Unresolved Matters

1. *Unresolved matters from 12/19/72 - 12/19/73*
review later

SUMMARY

2. *From the 12/19/72 - 12/19/73*
CP 2 will remain in list

SUMMARY

3.

SUMMARY

C. Status of Previously Reported Unresolved Matters

1. Bechtel Organization Chart for Midland Project

INSPECTOR RAR

SUMMARY OF PROBLEM Organization chart for Midland project not clear relative to lines of reporting responsibility & lines of command. Question status on completion of 1. Disc outlined

SUMMARY OF INSPECTION RESULTS

2.

INSPECTOR _____

SUMMARY OF PROBLEM

SUMMARY OF INSPECTION RESULTS

N 3. NE to 1/2 ...

Results of Inspection (continued)

2. Reactor Bldg No. 1

Straw
removal
in progress

Base slab - 6 forms - strain control

Tendon gallery - using 2 1/2" - good

Structural steel / shear steel (50%)

Rt Floor Rebar (15%) - 1/4" diameter plus OK

Backfill

- 2" diameter supports (I beams) - cast - OK

Carbide
removal OK

3. Reactor Bldg No. 2

Sand plastic
removed
satisfactorily

Being cleaned
Hydrolaser

Work slab - for base slab - exposed OK - good

Tendon gallery floor slab - good solidly - very good

Tendon gallery wall rebar (20%) (hard for some code
OK + the clay - some
in place (really not 100% clay
some places)

Backfill - one spec

Interlocks - flexible interlocks - good

4. Site Excavation & Backfill

Water pump
excavation
status? work
in progress

Structures excavation

> Backfill north of plant structures 25,000 CY - (Cl.)

> Excavation for water pond

No evidence of soil erosion problem or soil embankment
working site - removal of debris from site

Some debris other way - soil must have 1 structure
onto slab - into unbackfilled area etc

Must on part of any bldg from slab

- 13 -
Some mud and water adjacent to Unit 1 tendon gallery outer wall
(in future back-filled area)

Recheck info re 50 5500
in old log book vs old data
RPA volume

check latest
10 CFR 50 on this

Results of Inspection (continued)

(B) Condition of stored material components structures

1. Liner plate - consists of - 80x10' section (in section)

rusting - fairly heavy - 2' high bars -

scattered in various places

some debris, bolts, etc. - distributed

some of the logs (old letters - see book) are present

OLD WOOD STILL IN PLACE - some of

2. Anc' or bolts

3. Post tensioned truss rods - with the steel

4. Misc. steel -

a. Perfor. plates

b. S. G. plates

c. Reinforcing steel

LINER

PLATE PILES

liner plate -
some talk about
out floor
in place

Concrete Const. -
Some prop in side now

Results of Inspection (continued)

(4. Misc. Steel - continued)

d. Sump liners

e. Penetrations

f. Cadwell splices

g. SS pipe stored in barn - clean cover at top and at
4" (SCH 10) - 1-80A -
2" -
made in good condition - should
be in good condition

some moderate pipe size (24")

h. CS pipe - to be checked

4" }
304 }
SCH. 10 }

at top & bottom }
in good condition }

Results of Inspection (continued)

(C) Review of Inspection Procedures to be Used Prior to Restart of Construction

check force in CP response to ALAB-106

- 1. Existing concrete including embedded items ✓
- 2. Line plate (stored) ✓ (two locations)
- 3. Liner plate coating ✓
- 4. Reinforcing steel (embedded & stored) ✓
- 5. Post tensioning materials (in place & stored) ✓

CP will conduct soil analysis at ALAB-106

(D) Summary of results (get reports) of work done by Bechtel, and others to measure the environmental impact due to equipment and activities during const. delay.

see also...

- (1) Soil analysis to determine deposition of corrosive from chemical plant (Dow Chemical)
- (2) Atmospheric test coupons - CP...

(E) Action taken re ALAB-106

See separate entry

Report...

MID 192

Insp. Items - fr 6/26 - /73 insp:

① Condition of existing structure -

Alum Blk - placed concrete, masonry, formwork?
(condition, working, etc.)

R. Blk # 1 - brick wall, wood joist

R. Blk # 2 - brick wall, 7/8" wood joist

Ex. Blk - brick wall (CI) - possible soil erosion?

② Condition of steel work

Lower plate (if location)

Other steel, columns, connections, etc.

CS & SS joints - how SS part? inside?

③ Insulation for roof & exterior walls

④ Status of AAS - is it ...

⑤ % complete - check, ...

⑥ Budget of ...
QA - QC, ...

⑦ Steel ...

Thurs. Apr

RRR
MID 15

LUNCH
11 AM

See Tom C & Bob. We re attendees for spilt out
& Hill, Dodson - sufficient for me.
Kessler Ed. Hutton - B, Kerner (B)

MTG start
12:12

MTG items

- ✓(1) Route attendance list - as usual initial
- ✓(2) Agree, coord. & straighten out information - intent to do some. (1) (2) - other entries for comment.
- ✓(3) Plant rating? we have been using 662. Plus (each) 650 & 818
Whichever PSAR - or CP office rating? due in ~ 2 mo
- ✓(4) Status of major components? no time on for BAW - main contract part

RPU:	no time on for BAW
SG:	~ end of 74
Presser:	reported to arrive on 2.6

CRP's
- ✓(5) CP estimate of overall construction completion? 1 to 2% 1 to 2%
 other details of completion: - 70 days 32-35% of concrete
checking con. estimates, etc.
- ✓(6) Tags for nonconforming small & comp. - line plates, pin hangers, crane supports
 tag, rope off, some how segregate - tags line plate stock, for use in
 10 CFR 50, App B, you QA/QC party - re nonconf. small. - OK
 disc. briefly with Paul & Whitaker - Can you occur as of action - plans des
 can we consider this an open / in progress item? - to make it a sub-item.
 CP comment: yes - see
yes - no work started
- ✓(7) Wire ties on rebar - ^{inspect &} verify that they are strong enough to hold from rebar
 until concrete placement is completed.
 When walking & climbing on rebar, placement form, vibrator action, etc.
 CP comment: all ok via Bechtel - OK - review opt. when work compl.
- ✓(8) Cameras around "rings" - Dow stream - but + review - CME
 check this out - continue?
 CP comment: ok
- ✓(9) Backfill north of plant structure - what has been done to inspect NAD
 guid. chip areas - temp. of the surrounding Plains planned
- ✓(10) Status of some service water pond? excavated - mostly but not shaped - not hit road by debris
 inside cooling pond - a depressurized (no lines)
 most of impervious soil - no lines or d
- ✓(11) Would like to get copies of reports (Bechtel & others) regarding results
 of work done to measure effect of environment on small, components
 & structure during construction delay. Reviewed 2 yesterday

disc items

Bill Kessler

me - G
discussed
so ok

me - G

me - G

ok
com

⑥

Plans

under disc.
project - look on way
will improve on way
sampled - etc.

all to be requalified
(imp. first)

sample being taken
on panel N 511's
on 5000
• QC. bull pt.

CP - T. Cooke:

• QC paper for each line plate, punch, etc. - ITBC.

• considered \$ as newly rec'd - it requires imp. (recapit imp.)
due to long term storage at site.

Territory Subd.
for paper etc.
req -

late July for line plate

MIDLAND PROJECT
CONSUMERS POWER
EXIT MTG,
Attendance list

<u>Name (w/middle initial)</u>	<u>Title</u>	<u>Organization</u>
R. A. Rohrbacher	Reactor Inspector	AEC - RO
T.C. Coche	Project Supt	CPCO
W.E. Kessler	" Mgr.	"
R.E. Whitaker	Field OAE	"
C. Q. Hillis	QAA	CPCO
C. M. Galt	Reactor Inspector	AEC - RO
E. E. Felton *	PROJECT SUPT.	BECHTEL
C.E. → Buck Kinney *	Project Field O.C.	Bechtel
S.I. → John Peterson *	PROJECT QUALITY ASSURANCE ENG.	Bechtel

* Part time

Handwritten notes and scribbles in the top left corner.

411 D
ALAP-106

- Action being undertaken

Inventory
inspection
level of ground conditions.

Q. listed contents (Proc. 2.3 - p 1)

p. 2 Anchor bolts
embedded - one bldg.
stored - barn

Pool tower Thrusts
in place - RR #1

Sheathing
lim - stored in yard (ait.)


Bearing plates
in place

(4) One Bldg. Pipe Tunnel
stored - in yard

(5) Three Embed.
sole plates - Down RR 5ty.

Anchor Splices
part of thk. lim plate - stored in yard

Coatings
on-lim plate (grey) } on surface
pipe tunnel (orange)



Page 2.0 ps (A-AR-16)

627-7 RFR

(13)

Concrete - mixed, pump, seal.

See (the - and) deep 30 (p.1) ← here

Mr. M. J. ...
Murray & 41076 (app. dated May 21, 1973)

are higher concrete & reinforced walls.

anchors: vertical, major

to concrete, vertical

of one, they have already (stipulated only) -
been from (app. note) attached.

Creek description by walls:

1' creek width - location to

.010

.01 to .02

.02 to .03

.03 to .04

one .05

Typo: 2.04

Group - location to 1/2 mile creek.

Group -

~ 60'

~ 50'

~ 70' (75')

any other more significant for the same than described

ITBC - thick cut by part of the dirt from previous
conc. usually seen - with described

Concrete (cont.)


→ Below repl. sent in ALAB-106 repl. attached to response to section, etc. (Saggin future)
 - Affidavit of F. W. Joyce ^{Booklet} ^{dated} (6-15-73) covering June 14th inspection of ^{Unit} of R. Gate & F. Kaplan (both B) Tendon Access Gallery - Unit 1

① station 2+59
 (2, abut 3+45

" cracks shown in outside walls - all crack-verticall & predominantly Class 1 only 2 cracks, Class 4, ~ 86' apart (inner wall length gallery case - ~ 700 linear feet.

" cracks were normal drying shrinkage cracks - not unusual, exam. w/ 10X optical no evidence of other type motions - will not impair structural integrity

" Saggin future photo - appears to be same crack. (3+45) Joyce -



Make ITBC for next insp. - inspect rest of T.A.G. & other exposed concrete not visible

Earthquake

Soil borings - done
- week of 6-11-73

no results back yet

by Soil Materials & Engin

(SME)

with sup. of Bechtel

two
ground
areas

So. of aubley. - plant area

Dike area along T. River (SE from Exhilly)

(June) Plate Examination

Coatings - only done to date - (not plate wall.)
→ Carl's 2nd 11

→ cover in future report on the final Exam of

Final Plate Coatings

May 1 + 2, 1973

covered:
HCB
no spec 2
(concrete)

limited to thin plate accessible to unobstructing (10% sample
32 of 294)

visual, film thick (5 or more random locations)
using eleometer and mikrotester

future exp. & at least partial search will be done

H. L. Hondorp, Engin.

RD - note for later

Soil Analysis - important CP study (if ^{data} ^{gathered})

rain stations x 4 well compare

ground water & soil

done April & May 1970

rain data only - Cl⁻ as ppb

soil, water, soil, water

rain data only - Cl⁻ & sulfate, F

done July 1971

no evidence of det. effect of atom iten

→ more sampling to be done - chertom C also

Renie says y-

Brooklet People - stp, etc. occupation (Cant 1 - Alvin)

report + cadence - Brooklet - McDonald & ?
under pres. covered areas

High
H.L. Hendorp
(SFHO)

Mail work:

John Binkley
- Elsie Hunt
- Chuck Hunt

Chief Mail
- Chief work

CP:
in AAAB-106
rebar, conc, etc.

documentation

July 9 - Antenna
Tied to - (PT) ^{line} NDT work
conc. exp. - test strings

Jan 30, May 1-2 - Batch point -
lin. plate, etc.

May 8 - Conc. - out

June 11 - Soil borings


Jan 14 - wind cone - Tambora gal.

April 27 - CP - in USK.

Jan 18-20 - Batch point check-out - waste operations

Jan 27 - Scale calib. etc. batch point

North
←




Red Station
and ...

Gate ...

Tom ...
Mit ...

→ ...
Council



LEI

F75 57-372-1000
H 57-700-1000

11 'Island' 142

Carl E. Finney QC
John Peterson - D.S.

T.C. Cooke
Bruce Peck

35 MW.E. 1/10 get out
Dress 855 MW.E.
Horn 526 MW.E.

Commercial operations

Batch plant 99% ready to go

Champion installed and finished
operator plant not yet

FTL. masonry Lab will have beds
on concrete. Beds are at

#1 combustion 1/5000

#2 steam only 20000 turbine

- Bechtel installation

Bechtel - A.E. & construction

Canonie - Earthwork done 1/10

Line construction Bechtel now active

CP have say on bit work

NER - Bechtel also from CP

SW.W. may finish piping

Kellogg - small order at 95,000

G.E. high turbine

Have to

7/10 A.E.C. say want

look for today 1961

50 days from received, A
subside

AEC has heard & offered
-S.B. some work and

5/18 Appeals to be given
60 days to respond

Can appeal to Fed Court

Contracted to G.A. program of utilities
Construction materials etc

2. Tell what to do next 3 months

3. Review program and implement the
sub. Dual

4. NCR report on this & DRO
must submit

Rec'd

Corrosion
Inplace matls
Francis Joyce

Attn: Mr. Donald
Loggins
2 Christians

Carbo Zini-11 ^{Coating} Carboline 20

Equip. hatch -

Condenser air 11/2 pipes ^{Unit 2}
Spray coating with ^{Unit 1 on} and resprayed certain areas
Paper glued covered top matl.

Street pos. -


Reaction building ^{water}
Penetration - ^{Chloracem} ^{rod & post}

22791 SAK

.9A 82452 P1 2577

Very heavy rusting in pipe

flaking ^{1/2 in}
1190-102 Penetration



Crane rail support slab

Whitaker
Crane rail suff. 70-80
drilled in concrete
Structural Crane span between
horizontal supports
gray coating - inside contains
Pneumatics covers control panel
enclosure

2 Equip. hatches on site
down for containment base

3/4 by 1/2

At top for

with interior to be used as a trolley

Shims? use where they are

Flange plates with Peter G. ...
Personnel ...
Carboline coating v.g.

Life on way down over some ...

Paint inside coat 8' dia

about coat inside

orange epoxy paint 20.
1/2"

AM 2480

2 24 pins welded in body

4 per 2 long s.s.

Champion

Paul E.
D.
Paul E.

Calibrating scales

" H₂O measuring

test concrete mixes

Checking ^{air} vanes in truck

2 standby boards 8'

make up pipes and joints

comps and check 28 day

checks before production

5/6/2 - from [unclear] [unclear]
Circ water

5/5 - Concrete inspection

6/11 - Soil borings

6/14 - visual concrete condition

4/27 CP walls storage [unclear]

1/18, 19, 20 - match plan & check

was fine & seamless

Test Rebar 7/9 Interior PTH

J. Beitel } Civil inspection concrete

C. Hunter } Rebar & cover

DR0 - report of

Rebar & Cast-in-place

Ship & [unclear] dates don't agree

1974 Nov & Dec PTH [unclear]

ship & [unclear] in investigation

U. S. ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS

REGION III

Report of Construction Inspection

RO Inspection Report No. 50-329/73-05

50-330/73-05

Licensee: Consumers Power Company

212 W. Michigan Avenue

Jackson, Michigan 49201

License No. CPPR-81

CPPR-82

Category: A

Facility Name: Midland Plant, Units 1 and 2

Location: Midland, Michigan

415
462
22-11
? — Type of Licensee: PWR (B&W) Unit 1: 650 Mwe
Unit 2: 818 Mwe e

Type of Inspection: Special, Announced
(Restart of construction)

Dates of Inspection: June 26-28, 1973

→ Dates of Previous Inspection:

Principal Inspector: R. A. Rohrbacher

(Date)

Accompanying Inspector: C. M. Erb:

(Date)

Other Accompanying Personnel: None

Reviewed By:

SUMMARY OF FINDINGS

Enforcement Action:

A. Violations

No violations of AEC requirements were identified.

B. Safety Matters

No significant safety items were identified.

Licensee Action on Previously Identified Enforcement Matter :

No previously identified enforcement matter remained unresolved at the time of this inspection.

Design Changes:

No design changes were identified.

Unusual Occurrences:

No unusual occurrences were identified.

Other Significant Findings:

A. Current Findings

1. Facility Status

<u>Activity</u>	<u>% Completion</u>
Engineering	30-35%
Site construction	1-2%

2. Present Activities

Although new construction had not begun during the current inspection, about 50 people are at the site doing preconstruction and restoration work in preparation for the restart of construction. The work in progress included the removal of protective enclosures and materials from existing concrete slabs and structures, site clean-up, preliminary earthwork in the cooling pond area, renovation and testing activities at the concrete batch plant, inspection of construction work completed prior to construction shutdown, and the inspection of materials and components stored on or near the construction site during the shut-down period.

Both Consumers Power Company (CP) and the Bechtel Corporation (Bechtel) have established construction offices at the site.

B. Unresolved Matters

1. Requalification and Restoration of Site Stored Components

Carbon steel components stored ^{outside} at the site have rusted to varying degrees. Work and quality control procedures are being planned by CP to verify that all components used will meet applicable requirements. This matter remains open pending review of completed procedures. (Paragraph 1.)

2. Evaluation of Rebar Tie Wires

Due to the deterioration of some tie wires holding exposed reinforcing steel in place, the adequacy of these wires during concrete placement is not known. Inspection and evaluation of this matter are planned by the licensee. This matter will be reviewed during a subsequent inspection.

(Paragraph 2.)

C. Status of Previously Reported Unresolved Matters

Bechtel Corporation Organization For The Middle^{and} Project
(RO Inspection Reports No. 050-329/73-02 and 050-330/73-02)

In response to a request from RO:III during the referenced inspection, CP provided RO:III with a modified Bechtel organization chart. After a review of this chart (which was received by RO:III on May 7, 1973), and discussions with CP and Bechtel personnel during the current inspection, it was not clear to RO:III that all requirements of 10 CFR 50, Appendix B, Criterion I, were met. This matter remains open pending further clarification and/or changes.

← Management Interview

A. The following persons attended the management interview at the conclusion of the inspection:

Consumers Power Company

W. E. Kessler, Project Manager

C. Q. Hills, Quality Assurance Administrator

T. C. Cooke, Project Superintendent

R. E. Whitaker, Field Quality Assurance Engineer

Bechtel Corporation*

E. E. Felton, Project Superintendent

J. I. Dotson, Project ^{Quality Assurance} QA Engineer

C. E. Kinney, Project Field ^{Quality Control} QC Engineer

*Part time

B. Matters discussed and comments, on the part of management personnel, were as follows:

1. The present condition of the concrete structures poured prior to cessation of construction was discussed. The inspector stated that a visual inspection of the concrete in place and exposed for the Auxiliary Building and Reactor Buildings No. 1 and No. 2 was made and that this inspection verified the results and conclusions of reports by Mr. Joyce of Bechtel on this subject. The inspector further stated that the concrete observed appeared to be in good condition and that additional existing concrete would be inspected when form removal and cleanup is completed. CP stated that specialists from Bechtel will be used on a continuing basis to examine and evaluate the concrete and rebar.

In response to a question concerning the adequacy of the wire ties on rebar due to rusting, a representative of CP said that these tie wires would be inspected and that their holding power at various locations would be checked.

2. Procedures to requalify carbon steel components that had rusted during storage at the site were discussed. CP stated that plans are being made to requalify containment liner plates. The plates would be transported to a jig where cleaning and dimensional checks would be made. The plan would include a hold point for QC inspection prior to installation. At this point, if all applicable requirements were met, the plates would be considered acceptable for use; otherwise, the plates would be considered nonconforming.
3. The CP program of soil analysis and stored material wipe sampling was discussed. CP stated that this program was started in 1970 but halted during the construction shutdown. CP further stated that this program would be reinitiated, and an evaluation of the results would be made.
4. In response to a request, CP indicated that copies of reports would be sent to RO:III concerning results of work done to measure the affect of the environment on materials, components and structures during the construction delay.

5. The Bechtel organization for the Midland project was discussed with CP and Bechtel representatives. After a discussion on this subject, the inspection stated that he more fully understood the Bechtel organization chart but that it was not yet clear to him whether all requirements of 10 CFR 50, Appendix B, Criterion I, were met. Additional discussions on this matter are planned.

6. In response to a question regarding concrete batch plant status, CP stated that Champion, Inc. personnel were reactivating and requalifying the plant, and ^{that} calibration of measuring equipment and evaluation of ^{previously stored} materials (such as fly ash) for suitability were in progress.

REPORT DETAILS

Persons Contacted

The following persons, in addition to individuals listed under the Management Interview Section of this report, were contacted during the inspection.

Consumers Power Company

B. H. Peck, Field Supervisor (Mechanical)

Champion, Inc.

P. E. Schmansky, General Superintendent

L. P. M. C. Connell, Electrical & Safety Engineer

Bechtel Corporation

H. L. Hondorp, Engineer (Metallurgist)

R. L. McDonald, Engineer

Results of Inspection

1. Restoration and Requalification of Site Stored Components

Carbon steel construction materials and components stored outside at the site have rusted (corroded) to varying degrees. Rusting appeared to have progressed more rapidly on surfaces where water had collected. The rust appears to be fairly uniform on the surface

RUSTED

with no evidence of severe pitting. The licensee has arranged for specialists from Bechtel to inspect these components and evaluate whether the components can be restored to meet applicable requirements.

The following Class I (Q-listed) components were visually examined during the inspection of yard storage areas.

- a. Curved wall plates (containment liner) with ^{welded} ~~walled~~ on reinforcing bars.
- b. Containment penetration components.
- c. Steel bars with Cadwell^d ends (thimbles).
- d. Polar crane trolley.
- e. Polar crane wall supports and connecting track beams.

CADWELD

Surfaces of the above components, which will be within containment, were coated with a protective coating (Carbozine^c 11 or similar coating) prior to shipment to the site. This coating either prevented rusting or greatly inhibited its formation on these coated surfaces.

A A couple dozen stainless steel pipe sections, 2", 4", and 24" in diameter, were visually inspected in a warehouse. The pipe sections were free of surface dirt, end caps were in place, identification marks visible and ^{the pipe was} covered with plastic sheets.

All materials and components that have been stored at the construction site will be inspected, restored or rejected, and requalified prior to use or installation. Plans to develop procedures to do the above work are in progress.

2. Evaluation of Rebar Tie Wires

The inspector noted that the tie wires used to hold the reinforcing steel bars in place had varying amounts of rust on their surfaces. Rather severe rusting on some of these wires indicated possible weakness due to loss of material. A representative of the licensee stated that this condition would be evaluated to assure that the tie wires would hold adequately during construction activities including concrete placement.

3. Soil Analysis and Wipe Sampling Program

CP initiated the subject program early in 1970. Data were collected in the Spring of 1970 and in the Summer of 1971. The intent of this program was to determine the location and amount of chlorides and

at the size

other undesirable constituents which may adversely affect stored components. CP indicated that this program would be reinitiated.

4. Condition of Existing Structures and Stored Components

The status of the implementation of the CP program to determine the quality of the subject items is given in Appendix A of this report.

No 99 ->

It was determined from a visual inspection that this listing appears to represent the actual construction completed prior to construction cessation in late 1970.

Materials and components (Q-listed) stored at the site since cessation of construction has been categorized by the licensee. During the inspection of these stored Q-listed items, the inspectors determined that the listings appeared to be correct and that components not readily identified or obviously marked were subsequently identified upon return to the site office. Stainless steel piping was observed to be stored under plastic in a warehouse (barn) *at the site.*
~~near the construction area.~~

2. Evaluation of Present Condition

a. Concrete Work

A report was reviewed entitled "Interim Report on the Initial Examination of In-Place Materials, May 8 and 10, 1973" dated May 21, 1973 by F. W. Joyce, Supervising Civil Specialist, Bechtel (San Francisco). This report included the results of a visual inspection of the exposed structural concrete of the Auxiliary Building. The drawing which mapped visually significant ^a cracks was examined also. A visual examination of the concrete

CRACKS

structures and water stops ^{included in} ~~covered by~~ the above report, ~~during~~
~~the current inspection~~ indicated that the report results
were comparab^le to the actual conditions observed by the
RO inspector.

The affidavit of F. W. Joyce dated June 15, 1973, regarding
the June 14, 1973 inspection of concrete in the Unit 1 Tendon
Access Gallery, by Joyce, R. Grote and F. Kapla (all employees
of Bechtel) was reviewed. The results and conclusions in this
affidavit were in agreement with conditions observed and
conclusions reached by the RO inspectors during the current
inspection.

b. Concrete Batch Plant

The RO Inspector observed that the concrete batch plant and
concrete delivery trucks were in the process of renovation,
testing and requalification. Scales and other measuring devices
were being checked and recalibrated. This work was being done
by Champion, Inc. personnel. The licensee stated that test
mixes are scheduled for early July, 1973. *Pittsburgh Testing
Laboratory personnel will be at the site at this time
to sample and test these mixes.*

c. Reinforcing Steel

The licensee stated that two specialists from the Bechtel San Francisco office were presently onsite to examine reinforcing steel (exposed embedded and stored) to determine the extent of corrosion and material loss.

The RO inspectors visually examined the rebar in place for the Unit 2 Tendon Gallery walls. Except for surface rusting, the rebar appeared to be sound, free of severe pitting, and adequate for use. The licensee stated that inspection and testing of this (and other) rebar, as well as rebar tie wires, would be tested to verify that all applicable requirements are met prior to concrete placement in this area.

The licensee stated that their chief metallurgist and their chief civil engineer would be at the site during the week of July 2, 1973, to examine rebar, concrete and ^{other} related materials.

d. Earth Work

The licensee stated that some soil borings were made during the week of June 11, 1973, by Soils Materials and Engineering, with representatives of Bechtel present, but the results were not available yet. Some preliminary earth work has been started.

e. Containment Liner Plate Coating

A report was reviewed entitled "Interim Report on the Initial Examination of Liner Plate Coatings, May 1 and 2, 1973," dated May 18, 1973, by H. L. Hondorp, Engineer (Metallurgist), Bechtel (Ann Arbor). This report includes the results of the inspection of Newcomb, Grote and Hondorp (all of Bechtel) and Hinson (Coating Specialist, Carboline Company). A visual examination of about 25 liner plates (which may not be the same as those examined in ^{the} ^{report} above) during the current inspection indicated similar conclusions.

f. Containment Liner Plate

The licensee indicated that only a preliminary examination of these plates had been made recently but representative samples will be examined in the future. He further indicated that all liner plates would be reinspected, restored or rejected, and then, during a special QC inspection, requalified if all applicable requirements are met at that time. Plans to establish the above procedures are in progress.

g. Other Embedded and Stored Materials and Components

Items such as anchor bolts, polar crane supports, post-tensioning materials, cadweld material, according to the licensee, will be inspected, examined and measured, as appropriate, prior to use on installation.

During the inspection of the storage areas, it was observed that some material in storage had been restacked, relocated and/or recovered (during the last year or so) to provide satisfactory protection. It was further observed that new metal identification tags had replaced some hard-to-read *plastic over paper in plastic* tags.

U. S. ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS

REGION III

Report of Construction Inspection

RO Insp. Report: 50-329/73-05
50-330/73-05

Licensee: Consumers Power Company License No. CPPR-81
212 W. Michigan Ave Jackson, Mich. 49201 License No. CPPR-82
Category: A-2

Plant, Units:
Facility Name: Midland 1 and 2
Location: Midland Mich.

with license
492-8181

Type of Licensee: PWR (B&W) 800 MWE vol.
500 MWE 20% plus steam

Type of Inspection: Special Inspection
(Re-start of construction)

Date(s) of Inspection: June 26-28, 1973

Date(s) of Previous Inspection: None

Principal Inspector: R. A. Rohrbaker

(Date)

Accompanying Inspector(s): C. W. Eason

(Date)

(Date)

Other Accompanying Personnel: None

(Date)

Reviewed By: _____

(Date)

Summary of Findings

Enforcement Action

A. Violations

of AEC requirements.
No violations were identified.

B. Safety Matters

significant
No safety items were identified.

License Action on Previously Identified Enforcement Matters

No previously identified enforcement matter remained unresolved at the time of this inspection.

Design Changes

No design changes were identified.

Manual Corrections

No manual corrections were identified.

Other Significant Findings

A. Current Findings

1. Facility Status

<u>Activity</u>	<u>% Completion</u>
Engineering	30-35%
Site construction	1-2%

2. Present Activities

Although no construction had not begun since the

current inspection, about 50 people
pre-activities and activities were
at the site doing

pre-activities for the
re-start of construction. The work in progress
included the removal of protective enclosures
from existing equipment and structures,
and also site clean-up, and pre-activities

at the time of the inspection

inspection of equipment in a completed phase of
construction, and the inspection of

construction site during the shutdown period.

13. Unrecorded Matters

1. Storage of the Construction Materials for the Reactor (Containment) Buildings

All Carbon steel materials, especially painted surfaces have rusted. (Para 1)

2. Condition of Tie Plates Holding Reinforcing Steel Bars These wires were quite rusty, and their ability to hold under concrete pour conditions must be evaluated. (para 2)

(Bec. 701) more extensive investigation of the site.

to verify that all components used will meet applicable requirements.

B. Unconcern Factors

1. Regulation and Restoration of Site Stored Components

Due to the fact that components stored at the site have varied ^{to varying degrees} work and quality control procedures are being planned. This matter remains open pending review of completed procedures. (Paragraph 1)

2. Evaluation of Rebar Ties

Due to the deterioration of some ties which have been exposed to the weather, it is planned to place ties during construction. Inspection and maintenance of the ties will be planned by the contractor. This matter will be reviewed during a subsequent inspection.

C. Status of Previously Reported Unresolved Matters

Bechtel Corporation Organization for the Middle East
 (RO Inspection Reports No. 050-379/12-02 and 050-330, 78-
 In response to a request from RO:III during the
 referenced inspection, CP provided RO:III with a
 certified Bechtel organizational chart for a period
 of 180 days which was reviewed by RO:III
 (May 7, 1973) and discussions with CP and RO:III
 personnel during the same inspection. It was
 not clear to RO:III that all requirements of
 10 CFR 50, Appendix B, Category I, were met. The
 matter remains open pending further information
 and/or changes. (Para 5)

C. Status of Previously Reported Unresolved Matters

Management Interviews

The following persons attended the management interviews at the conclusion of the inspection.

Consumers Power Company

W. E. Kessler

Project manager

C. D. Hill

Quality Assurance Administrator

T. C. Cooke

Project Superintendent

R. E. Whitaker

Field Quality Assurance Engineer

Bechtel Corporation

E. C. Felton

Project Superintendent

J. I. Dutton

Project S.A. Engineer

C. E. Kinney

Project Field Q.C. Engineer

* Not time

their holding power at various locations would be checked.

2. The inspector noted that ^{some of} the containment liner plates had ^{recently} been identified with metal tags. The Cooke of CP stated all plates would be transported to a jig where cleaning and dimensional checks would be made. All discrepancies ^{at this hold joints} require that a non-conformance report be issued. The Cooke described their procedure as a 100% requalification of the blimp tapes. All original markings would be retained to assure traceability of heat, and also sequencing of reactions. The inspector stated these materials will be followed on subsequent inspections.

3. The inspector discussed the Q.A./QC organization with CP and Bechtel representatives.

4. The status of the concrete batch plant was requested by the inspectors. Mr Cook of CP stated that Champion Inc. were reactivating and recalibrating ^{the plant} the measuring equipment was unobtainable and left over materials such as fly ash were being evaluated for suitability. The transport trucks were having the vanes, and other agitation equipment reworked. They plan to produce concrete test mixes the first week in July and 28 day test results will be available prior to the pouring of production concrete.

1. Construction Materials Storage

The unit appears to be ^{primarily} with no evidence of heavy fitting. Some times, where water had collected, showed a heavier rust, than those where the water had drained. The licensee has arranged for Bechtel specialists to evaluate whether the materials are suitable and have sufficient wall thickness of ^{the} ^{reactor} ^{remained} and ^{disposal}. The following ^{are} ^{not} items were inspected, with all surfaces ^{intended} to be ^{insulated}:

The reactor building ^{is} ^{coated} with ^{Calcium-silicate} or similar ^{material}. ^{It} ^{is} ^{curved} ^{part} ^{of} ^{the} ^{building} ^{line} with ^{welded} ^{on} ^{reinforcing} ^{bars} (2) Partitions ^{of} ^{building} ^{line} (3) Steel ^{beams} with ^{rod} ^{welding} ^{beads} ^{attached} (4) Trolley for the ^{pole} ^{crane}

(5) Pole crane with supports and connecting ^{truss} ^{beams} (6) Few pieces, stored indoors, of ^{the} ^{system} ^{stainless} ^{piping}

2. Corrosion of Tie Wires

The tie wires for the reinforcing steel rods had varying amounts of rust. [This is to be expected, since some were underwater, some above water (and some with an alternating wet and dry condition).] The Bechtel Q.C. representative stated that a careful evaluation would be made to assure that the tie wires would hold through all construction activities including concrete pouring.

B. Matters discussed and comments, on the part of management personnel, were as follows:

1. The present condition of the concrete structure poured prior to construction of concrete was discussed. The inspection of the concrete and inspection of the concrete in place and exposure for the Amplifier Building, of the concrete structure and No. 2 was made and that the inspection verified the results and conclusions of reports by Mr. Joyce of the condition of the concrete. The inspection further stated that the concrete

observed appeared to be in good condition and that existing conditions would be inspected in the form removed and repaired as necessary.

CP etc. The specimens from the concrete were examined on a continuous basis to determine the concrete and steel. A question concerning the condition of the

wire ties on rebar due to rusting, a representative of CP said that these tie wires would be inspected and that their holding power in concrete would be checked.

- 2. Procedures to requalify carbon steel components that had rusted during storage in the site were discussed. CP stated that plans are being made to ^{requalify} containment time periods. The plates would be transported to a shop where cleaning and dimensional checks would be made. The plan would include a ~~site~~ held point of

QC inspection prior to installation. At this point, if all applicable requirements were met, the plates would be installed. Following placement, the plates would be inspected for proper curing.

3. The CP program of soil analysis and other material wise sampling was discussed. CP stated that this program was started in 1970 but halted during the construction activities. CP further stated that the program would be reinstated, and ~~appropriate~~ evaluation of the results would be made.

4. In response to a request ~~for~~ ^{to} ~~provide~~ ^{would be sent to} individuals that copies of reports ~~from~~ ^{of} ~~various~~ ^{various} ~~amounts~~ ^{amounts} of work done to measure the ~~status~~ ^{status} of the environment in materials, composition and structures during the construction activity.

3. The possible organization for the material program was discussed with CP and BAA. After a discussion on this subject, the ~~group~~ ^{group} stated that ~~it~~ ^{it} ~~was~~ ^{was} ~~more~~ ^{more} ~~likely~~ ^{likely} ~~that~~ ^{that} ~~the~~ ^{the} ~~material~~ ^{material} ~~program~~ ^{program} ~~be~~ ^{be} ~~organized~~ ^{organized} ~~by~~ ^{by} ~~the~~ ^{the} ~~CP~~ ^{CP} ~~and~~ ^{and} ~~BAA~~ ^{BAA} ~~to~~ ^{to} ~~provide~~ ^{provide} ~~the~~ ^{the} ~~material~~ ^{material} ~~program~~ ^{program}.

was yet clear to him whether all requirements of OCFR 50, 23000.03, Criterion I, were met. Additional discussion on this matter on 1/10/68.

- 6. In response to a question regarding concrete total plant status, it was stated that Champion ^{personnel} were reactivating and requalifying the plant, & calibration of measuring equipment and calibration of analytical functions. The work for suitability was in progress.

101

Report Details

Persons Contacted

The following persons, in addition to individuals listed under the Management Interview section of this report, were contacted during the inspections.

Consumers Power Company

B. H. Peck, Field Supervisor (Mechanics)

Champion, Inc.

P. E. Schmansky, General Superintendent
L. P. Mc Connell, Electrical & Safety Engineer

Bechtel Corporation

H. L. Hondorp, Engineer (Metallurgist)
R. L. McDonald, Engineer, Sr. Consultant

Results of Inspection

1. Restoration and Requalification of Site Fixed Components

~~inspected~~ Carbon steel (including materials
 and composite storage ^{outside} tanks have rusted
 (corroded) to varying degrees. Pitting
 appears to have progressed more rapidly on
 surfaces where water had collected. The
 rust appears to be fairly uniform on the
 surface with no evidence of severe pitting.
 The licensee has arranged for inspection
 from Bechtel to inspect these components
 and evaluate whether the components are
 suitable for continued operation.

A The following items (A-1000) components
 were visually examined during the inspection
 of yard storage areas. ~~_____~~

(a) ~~_____~~

working in reinforcing beams

(b) continuous penetration components

(c) ~~Steel pipe with Cadwell ends (thinning)~~

(d) ~~Steel pipe with~~

(e) Polar cross wall supports and connecting back beams

Surfaces of the above components, which will be within containment, were originally coated with a protective coating (Corrosion or similar coating) prior to shipment to the site. This coating with the present coating or paint inhibited its function on these containment components.

or similar coating)

coupling 5"

11. A ~~number~~ of standard steel pipe sections, 2", 4" and 8 1/2" in diameter, were used in a work area. The pipe sections were free of surface rust, and caps were in place, identification number visible and

check
re 5000
5/12

covered with plastic sheets.

~~No. 77 Special instructions, also stored in the warehouse, were protected with...~~

All materials and components that have been stored at the construction site will be inspected, tested as required, and requalified prior to use as indicated in Plans to describe procedures to all the above work are in progress.

2. Evaluation of Rebar Tie Wires

The inspection indicated that the tie wires were to hold the reinforcing steel bars in place but varying amounts of rust on their surfaces. Further investigation of these wires in the ~~that~~ ~~indicated~~ ~~points~~ ~~where~~ ~~the~~ ~~is~~ ~~of~~ ~~quality~~. A representative of the

licensee stated that the conditions would be evaluated to assure that the tie wires would hold adequately during construction activities including concrete placement.

3. Soil Analysis and Wipe Sampling Program

CP initiated the subject program early in 1970. Data were collected in the spring of 1972 and in the summer of 1971. ^{The intent of the program was to determine} the location and amount of chlorides and other undesirable constituents which may adversely affect a structure. CP indicates that this program will be reinitiated.

4. Condition of Existing Structures and Foundation

The status of the implementation of the CP program to determine the quality of the subject structure is given in Appendix A of this report.

APPENDIX A

Prepared by

Printed by

The following persons in addition to individuals listed in the Management Report on the subject of the work, were consulted during the preparation of this report.

B. H. Park, Field Supervisor (Construction)

Boyle Corporation

H. J. Hunter, Engineer (Mechanical)

R. L. McDonald - Sr. Comm. Eng.

Results of Inspection

State of Implementation of Condition 1 of NACB-1966

1. Listings

related to nuclear safety (Q-list)
Previously completed construction projects have
been listed by CP,
and the listing has been grouped
under the following headings: Aviation,
Banking, Marine, Banking, Steel, Road, and
and Fire, Escalators and Buildings.

11 A

→ It was determined from a review of the listings that
the listing appears to represent projects which were
completed prior to 1966 (Q-listed)

A. Materials and components of these projects
and construction of construction have been categorized

by the licensee. During the inspection of these listed Q-listed items,

A. the inspectors determined that the listings appeared
to be correct and that components not readily
identifiable or obviously marked were subsequently

identified upon return to the site office.

→. Evidence still being was
observed to be strong under pressure in a
variety of places near the construction area.

2. Evaluation of Test Conditions

a. Concrete Test

A report titled "Interim Report on the Test

Specimens of the Main Wall at the
dated May 21, 1973.

and 10, 1973," by F. W. Geyer,

Supervising Civil Engineer, (So

fracture, the report indicated the
of a small suspension of the ^{exposed} concrete

concrete of the main building. The

which appear visually significant cracks were

examined and found to be


to be sound, free of severe pitting, and
adequate for use. The licensee stated that
inspections and testing of this (and other) rebar,
as well as rebar tie wires,
would be tested to verify that all applicable
requirements are met prior to concrete
placement in this area.

b. Concrete Batch Plant

The PD Inspector observed that the concrete
batch plant and concrete delivery trucks
both prior to the process of batching,
and testing and regularization. Scales and
other measuring devices were being checked
and re-calibrated. This work was being done by
Champion, Inc. personnel. The inspector noted
that test mixes are scheduled for calibration.

c. Reinforcing Steel

The licensee stated that this
specimens for the batch plant. The specimens
were on site to examine the
specimens for pitting, etc. () to determine
if the rebar is suitable for use.



7 The license stated that their chief metallurgist and their chief civil engineer would be at the site from July 7, 1978, to examine records, drawings and other materials.

d. Earthwork

The license stated that some soil borings were made during the week of June 11, 1978, by Soils, Materials and Engineering, with the following personnel: The borings were not examined yet.

~~and all of the surrounding area.~~

Some preliminary soil samples were taken in the area of the site. (not a formal report)

Containment
e. Lead Plate Coating

A report was received July 11, 1978, from the site dated June 18, 1978, of Lead Plate Coating. The report was dated May 18, 1978, by H. L. Honder, Engineer (Metallurgical Engineering) (New York). This report includes the results of the inspection of the site and the results of the soil borings. The report also includes a photograph of a lead plate coating of about 20 feet (which was not for the site) and a photograph of a lead plate coating of about 20 feet. The report also includes a photograph of a lead plate coating of about 20 feet.

f. Containment Area Plate

The license indicated that only a preliminary examination of these plates had been made, but representative samples will be examined in the laboratory. No further action that the plates would be re-inspected, restored or rejected, and then, during an official inspection, regardless of any other requirements are met at that time. Plans for the above procedures are in progress.

Embedded and

g. Other Items

Items such as work tools, pole, work supports, post-tensioning cables, and material according to the license and inspection, and as required.

7. During the inspection of the storage area, it was determined that some material had been re-stocked, and it was necessary to provide some additional information.

No 9

It was further observed that some articles
identified to date had not been
hand to read papers in the past.