

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A B V S 1 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 01 REPORT SOURCE L 0 5 0 0 0 3 3 4 7 0 7 1 8 8 0 3 0 7 2 1 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 We have determined that an undersized snubber has been installed on the Recirculation
03 Spray line from the 1A Heat Exchanger to its 180 degree spray header. Failure of this line
04 during a seismic event would result in loss of flow to 25 percent of these spray
05 headers. The remaining 75 percent of these spray headers and the quench spray system
06 would provide adequate protection.

09 SYSTEM CODE S B 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE S U P P O R T 14 COMP SUBCODE D 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 0 EVENT YEAR 8 0 SEQUENTIAL REPORT NO. 0 5 0 OCCURRENCE CODE 0 1 REPORT TYPE T REVISION NO. 0
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 22 NPRO-4 FORM SUB N 24 PRIME COMP SUPPLIER A 25 COMPONENT MANUFACTURER G 2 5 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 This deficiency was determined during an investigation resulting from NRC IE Bulletin
11 79-14. The snubber will be replaced with a snubber of the correct size.

15 FACILITY STATUS H 28 % POWER 0 0 1 0 29 OTHER STATUS 30 Design METHOD OF DISCOVERY C 31 Operator observation 32
16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36 N/A
17 PERSONNEL EXPOSURES NUMBER 0 0 0 0 37 TYPE Z 38 DESCRIPTION 39 N/A
18 PERSONNEL INJURIES NUMBER 0 0 0 0 40 DESCRIPTION 41 N/A
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43 N/A
20 PUBLICITY ISSUED N 44 DESCRIPTION 45 N/A

NAME OF PREPARER W. S. Lacey PHONE 412-643-1258

800725033/