

REGULATORY DOCKET FILE COPY

JUL 8 1980

Point Beach Units No. 1&2  
Docket Nos. 50-266  
-301

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

Wisconsin Electric Power Company  
231 West Michigan Avenue  
Milwaukee, Wisconsin 53203

Gentlemen:

SUBJECT: POTENTIAL WELDING DEFICIENCIES IN TANKS FABRICATED BY GRAVER  
TANK AND MANUFACTURING COMPANY

You were informed by the NRC resident inspector on June 25, 1980 of potential welding deficiencies in tanks fabricated by Graver Tank and Manufacturing Co. that could possibly result in loss of piping integrity at the pipe to tank connection during ASME Service Level D loading conditions (e.g., seismic). Welds in tanks were found at the Beaver Valley plant which, at the pipe to tank connection, were not in accordance with drawings and, at seam locations, contained unacceptable discontinuities. Quality assurance records stated the welds were in accordance with the drawings and of acceptable quality.

You are requested to determine if the weldments in safety-related tanks at Point Beach Units No. 1&2 fabricated by Graver Tank meet design specifications and fabrication requirements. Verification of weld type (i.e., seal or full penetration) and soundness must be done by independent nondestructive inspection and review of available construction radiographs, not through reliance on Graver inspection records. Should NDE of the pipe connections be impractical during plant operation, the inspections may be deferred to a scheduled refueling outage if the piping integrity can be demonstrated by analysis assuming a joint configuration such as that labeled "as found" in Enclosure 1 or there is evidence of independent inspections of work in progress by the licensee during the fabrication of the tank. If welds are found which do not meet design specifications or fabrication requirements, describe the corrective actions that will be taken.

This information is requested under the provisions of 10 CFR 50.54(f). Accordingly, you are requested to provide within twenty (20) days of the

OFFICE ➤							
SURNAME ➤							
DATE ➤							

JUL 8 1980

Wisconsin Electric Power Co.

2

date of this letter, written statements of the above information, signed under oath or affirmation, to the NRC Regional Office with a copy to IE:HQ which will enable the staff to determine whether or not your NRC license to operate your nuclear power generating facility should be modified, suspended or revoked.

Sincerely,

Norman C. Moseley,  
Director  
Division of Reactor  
Operations Inspection  
Office of Inspection  
and Enforcement

Enclosure: As stated

bcc: H. D. Thornburg, IE  
D. G. Eisenhut, NRR  
R. H. Vollmer, NRR  
V. S. Noonan, NRR  
T. Novak, NRR  
G. W. Reinmuth, IE  
B. H. Grier, RI  
RONS Branch Chiefs  
RCES Branch Chiefs  
S. S. Pawlicki, NRR  
D. C. Boyd, RIII  
D. Danielson, RIII  
D. Beckman, RI  
L. Tripp, RI  
W. F. Sanders, RI  
R. F. Warnick, RIII  
C. M. Trammell, NRR

DISTRIBUTION  
Docket Files (2)  
Central Files  
IE Files  
RAHermann Rdg Files  
NCMoseley Rdg Files  
ROI Rdg Files  
tp Rdg Files

OFFICE ➤	IE:TP	IE:TP:AD	IE:ROI:D			
SURNAME ➤	RAHermann:mkm	ELJordan	NCMoseley			
DATE ➤	7/1/80	7/1/80	7/1/80			

## CALCULATION IDENTIFICATION NUMBER

J.O. OR W.O. NO.

17640.4

DIVISION &amp; GROUP

EMO - Mechanical

CALCULATION NO.

S1-12A

OPTIONAL TASK CODE



PAGE 3

INTRODUCTION

CONNECTION NI OF B.V. UNIT 1 REFUELING WATER STORAGE TIC WAS NOT INSTALLED AS REQUIRED BY F-11-650 OR BY STKHE & WEBSTER PROCUREMENT SPEC B.V.S-183. THE SPEC. REQUIRES A FULL PENETRATION WELD BETWEEN THE NOZZLE NECK & SHELL AND BETWEEN THE NOZZLE NECK & REINFORCING PAD; IT ADDITIONALLY REQUIRES THAT THE PAD-NECK FULL PENETRATION BE CAPPED WITH A FILLET & REQUIRES A CIRCUMFERENTIAL PAD-SHELL FILLET AROUND THE OUTSIDE OF THE PAD.

THE TR. MFGR. DID NOT COMPLETE THE PENETRATION WELDS; THEREFORE THE ONLY WELDS HOLDING NI TO THE PAD & SHELL, ARE THE FILLETS.

## CONNECTION NI AS REQUIRED BY BVS-183

"As-Fabric" Condition

SECTION B-TB

"NO WELD MITAL"

→ THIS CALCULATION CHECKS THE STRESSES IN THE FILLETS CAUSED BY OBE FABRIC LOSS