LICENSEE EVENT REPORT

| LICENSEE EVENT REPORT |
|--|
| CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
| 0 1 M A Y K R 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 65 65 CAT 58 |
| REPORT LL 6 0 5 0 0 0 0 2 9 7 0 6 3 0 8 0 8 0 7 3 0 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During a maintenance outage in Mode 5 while performing a Class "C" Test |
| on trip valve TV-401D valve leakage exceeded T.S. 3.6.1.2.b limits. This |
| o 4 is the first event of this nature. The trip valve is in the secondary sy |
| stem, and both primary and secondary system pressures were below 300 psi |
| [0]6] g. Based on the above discussion there were no adverse effects on the pu |
| [0]7 blic health or safety. |
| 0 8 6 |
| SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SU |
| CODE TYPE NO. O O O O O O O O O |
| The root cause of this event was foreign material under the valve seat. |
| [1] [The valve is a Masoneilan 2" air operated globe valve. The valve was is] |
| olated and the material removed. The valve was successfully retested. N |
| o further actions are planned at this time. |
| 7 8 9 |
| FACILITY STATUS SPOWER OTHER STATUS 30 METHOC OF DISCOVERY DESCRIPTION 32 1 5 G 28 0 0 0 0 29 NA B 31 Class "C" Test 80 |
| ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 7 8 9 10 11 PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA 45 LOCATION OF RELEASE 36 NA 80 |
| 7 8 9 PERSONNEL INJURIES 13 NA |
| NUMBER DESCRIPTION (41) NA NA NA NA NA NA NA NA NA N |
| TYPE DESCRIPTION NA NBC USE ONLY |
| POBLICITY AS INCOSE ONLY ISSUED DESCRIPTION 45 NA 68 69 NA 68 69 |
| 800805005/ Lester D. French PHONE: (413) 625-6140 |