

LICENSEE EVENT REPORT

EXHIBIT 7

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	T	N	S	N	P	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30

0 1	L	0	5	0	0	0	3	2	7	0	6	2	3	8	0	0	7	3	1	8	0		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Unit 1 in mode 3, RCS temperature 538°F and pressure 1725 psig.

0 3 | Inadvertent SI caused the boron injection tank to fall below the

0 4 | boron concentration required for mode 3.

0 5 | No previous occurrences. There was no danger to health and safety

0 6 | of the public as no radiated fuel was onsite.

0 7 | _____

0 8 | _____

0 9	C	C	A	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

17	8	0	1	1	2	0	3	L	0
21	22	23	24	25	26	27	28	29	30

Z	Z	Z	Z	0	0	0	N	N	Z	Z	9	9	9
34	35	36	37	38	39	40	41	42	43	44	45	46	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (24)

1 0 | When contents of BIT were pumped into the reactor coolant system,

1 1 | borated water from the RWST was pumped in by charging pumps. The

1 2 | boric acid transfer pumps were realigned to recirc. through the BIT

1 3 | from boric acid storage tank to restore concentration. Boron

1 4 | concentration returned to within Tech. Spec. limits on 6/25/80.

1 5	B	0	0	0	N/A	A	Operator observation
7	8	9	10	11	12	13	14

1 6	Z	Z	N/A	N/A
7	8	9	10	11

1 7	0	0	0	Z	N/A
7	8	9	10	11	12

1 8	0	0	0	N/A
7	8	9	10	11

1 9	Z	N/A
7	8	9

2 0	N	N/A
7	8	9

NAME OF OPERATOR: Daniel J. Record PHONE: 615-842-5208