NOCKET Files

JUN 6 1972

27-201

J. M. Hendrie, Deputy Director for Technical Review Directorate of Licensing

TECHNICAL ASSISTANCE REQUEST FOR REVIEW OF PROPOSED REPAIR PROCEDURES FOR BAW CONTROL ROD DRIVE MOTOR TUBE DISCONTINUITIES

Babcock & Wilcox (B&W) informed the AEC at a May 11, 1972 meeting in Bethesda that many of the control rod drive (CRD) motor tubes on all plants having Baw NSSS are suspect of containing hot tears on the inside tube surface. Baw is currently assessing the need for repair or replacement of some of these CRD assemblies. They tentatively proposed several methods for repairing these CRD motor tubes some of which would involve exemptions from ASME code requirements. Other possibilities are to lower the design requirements for these motor tubes or present a fracture mechanics analysis to show the acceptability of the existing motor tubes with these discontinuities. The assistance of the Mechanical Engineering Branch in the review of the proposed repair procedures and design requirements for B&W control rod drive motor tubes is requested. In this regard, it is also requested that the Mechanical Engineering Branch be represented at the June 6, 1972 meeting in Lancaster, Ohio at Diamond Power's CRD manufacturing facility. Any questions regarding this matter should be directed to I. Peltier (Extension 7548) of PWR Branch No. 4.

Original signed by A. Giambusso

A. Giambusso, Deputy Director for Reactor Projects Directorate of Licensing

cc: F. Schroeder, L

R. C. DeYoung, L R. R. Maccary L

D. Knuth. L

W. McDonald, L

R. W. Klecker, L

A. Schwencer, L D. Lange, L

I. A. Peltier, L

D. Davis, L

DISTRIBUTION

Central Files

Docket Files (50-269/270/287/346/404/5405/289/320

302/329/330/312/313)

L Reading

PWR-4 Reading

OFFICE >	L:PWR-4	L:PWR-4	L:AD/PWRs	L:ADRP	
	DKO	ASchwencer	PCTA SAL	AGiambusso	Men
DATE	6/2/72	6/2/72	6/3 /72	6/ /72	