

Central File

SEP 21 1976

F. J. Long, Chief, Reactor Operations
and Nuclear Support Manager, IE:II

INSERVICE INSPECTION OF CLASS 2 PIPING, CRYSTAL RIVER UNIT NO. 3
DOCKET NO. 50-302 (ITEM 1.1046ML)

We have reviewed the recommendation transmitted with the subject action item, and the referenced inspection reports, and have the following comments.

1. NER is making a vigorous effort to implement the standardization concept with respect to Technical Specifications, and is very reluctant to add unique special requirements which apply only to a specific part of the facility.
2. Although the preservice examination may be performed to Section XI 1971 with Addenda through Winter 1972, 10 CFR 50.55a(g) requires periodic updating of the ISI program.
3. UT is still a developing technique, and "geometric" reflectors are not uncommon. It appears to us that the licensee has given much further than most organizations in supporting the conclusion that the reflectors are geometric indications rather than flaws.
4. We note in Report 50-302/76-2 (page I-2) that some ultrasonic reflectors "... appeared to have grown, i.e., increased in length . . ." between examinations conducted before and after hydrostatic test. We find no further discussion of this observation.

POOR ORIGINAL

10502
4

8003170525

SEP 21 1976

F. J. Long

- 2 -

In our opinion, this observation requires resolution by IE:II and the licensee. It has been suggested that the reflectors may be small enough to be acceptable to the Code Rules under which the examination was conducted.

Even though the flaws may be of an acceptable size, we believe the situation warrants further investigation, since the code definition of "acceptable" flaw size is intended to accept only those flaws which would not reasonably be expected to grow during the service life of the component. If reflectors of "acceptable" size are, in fact, growing as a result of one pressure cycle, it would appear necessary to reconsider their acceptability.

It has also been suggested that the apparent increase in reflector size may not be real, and may represent apparent differences which are in reality within the limits of measurement accuracy. Whatever the facts are, we believe that the subject needs to be resolved by IE:II and documented in a future inspection report.

Original signed by
K. Seyfrit

Karl V. Seyfrit, Chief
Reactor Technical Assistance Branch
Office of Inspection and Enforcement

cc: G. Key, IE:HQ
L. C. Lewis, IE:II
A. R. Herdt, IE:II

POOR ORIGINAL

Distribution:
IE Files ✓
IE Reading
RIP Reading
RTAB Reading
KXXXXXX
JB Henderson

E21046H1 RIP 879

OFFICE →	RIP:RTAB	RIP:RTAE				
DE-SURNAME →	JB Henderson	KV Seyfrit				
DATE →	9/21/76 cd	9/21/76				