

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 30 1975

Consumers Power Company
ATTN: Mr. Stephen H. Howell
Vice President
1945 West Parnall Road
Jackson, Michigan 49201

Docket No. 50-329
Docket No. 50-330

Gentlemen:

Enclosed is IE Bulletin No. 75-06 which requires action by you with regard to your power reactor facilities with operating license or construction permit.

Should you have questions regarding this Bulletin or the actions required of you, please contact this office.

Sincerely,

James G. Keppler
Regional Director

Enclosure:
IE Bulletin No. 75-06

Approved by GAO, B-180225 (R0072), clearance expires 7-31-77. Approval was given under a blanket clearance specifically for identified generic problems.

bcc: Central Files
IE Files
PDR
Local PDR
OGC, Beth, P-506A
R. Callen
W. North
M. Cherry

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES



0006160 394

①

A0
(2)

RM

May 30, 1975
IE Bulletin No. 75-06

DEFECTIVE WESTINGHOUSE TYPE OT-2 CONTROL SWITCHES

Description of Circumstances

The Westinghouse Electric Corporation recently reported to the NRC the finding of a number of defective Westinghouse type OT-2 electrical switches in the main control board of the Sequoyah Station. The defective switches were found during installation of the main control board of the Sequoyah Station, which is currently under construction.

The defective switches are of a spring-return-to-neutral type. Manual operator action of the switch involves rotating the switch clockwise or counterclockwise, and an internal spring force returns it to the central neutral position. Westinghouse reported that internal friction caused some switches to bind and fail to return to the neutral position, due to an adverse tolerance stack-up on internal switch components.

Corrective action has been taken to replace the defective switches in the Sequoyah Station. Westinghouse has issued a Technical Bulletin to utilities with Westinghouse NSSS's in operation, advising them of the potential for similar defective switches in these facilities. These switches may also be installed in other nuclear power facilities.

In case of uncertainty, licensees are advised to contact the Westinghouse Control Products Division regarding test instructions and replacement procedures for these switches.

Action to be Taken by Licensees

For all power reactor facilities with operating license or construction permit:

1. Determine if switches of the type described above are in use, or planned for use, in safety related systems of your power reactor facility(ies).
2. Notify this office in writing, within 30 days for facilities with an operating license and within 60 days for facilities with a construction permit, of the results of your findings with regard to item 1, above.
3. If switches of the type described are in use or planned for use in safety related systems, include in your written reply to this Bulletin the extent of their use and the actions you have taken or plan to take to prevent malfunction of the type described above. Your written reply should include the date(s) when your actions in response to this Bulletin were or will be completed.

duped - 08
7909200059