

TIC



SMUD

SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

June 10, 1980



Mr. R. H. Engelken, Director
Region V, Office of Inspection
and Enforcement
U.S. Nuclear Regulatory Commission
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, CA 94596


Docket 50-312
Rancho Seco Nuclear Generating
Station, Unit No. 1
IE Bulletin 80-06

Dear Mr. Engleken:

IE Bulletin 80-06 requested certain information regarding the Engineered Safety Feature (ESF) reset controls at Rancho Seco Unit No. 1. A review of electrical drawings has been made to determine that all equipment actuated by the Safety Features Actuation System remains in its emergency mode when the actuation signal has been reset. Testing of the actual installed equipment at Rancho Seco has been completed for that equipment which can be tested when the plant is in operation. The equipment tested and the test procedures used are listed below. This testing was not conducted specifically in response to the bulletin but the results satisfy the requests made in the bulletin. The remaining equipment cannot be tested until the plant is in a cold shutdown condition, and we therefore cannot commit to perform this testing until the plant is in an extended shutdown or at the next refueling, whichever comes first.

<u>Equipment</u>	<u>Test Procedure</u>
P-236 Makeup Pump	STP 843
P-238 High Pressure Injection	STP 847
SFV-22023 Letdown Line	STP 848
SFV-23604 Makeup Line	STP 865E
SFV-23809 High Pressure Injection	STP 865A
SFV-23810 High Pressure Injection	STP 865B
SFV-23811 High Pressure Injection	STP 865C
SFV-23812 High Pressure Injection	STP 865D
SFV-23645 Makeup Pump Recirculation	STP 844
SFV-25003 Decay Heat Pump Suction	STP 853
SFV-23508 Makeup Tank Isolation	STP 850

The above tests verified that 1) the operator could not take manual control of the device while the ESF signal was actuated, 2) that the device remained in the ESF state after the ESF signal was reset, and 3) that the operator could take manual control of the device after resetting the ESF signal.




Mr. Engelken

-2-

June 10, 1980

The drawing review which has been completed and the testing done to date indicate that all safety related equipment remains in its emergency mode upon reset of a safety features signal at Rancho Seco. For this reason, the District does not propose any modifications, design changes, or other corrective actions at this time. If the remaining testing which is to be completed by the end of the next refueling outage indicates otherwise, the District will inform you of a proposed schedule for any corrective actions at that time.


Respectfully submitted,



Wm. C. Walbridge
General Manager

cc: Office of Inspection & Enforcement
Division of Reactor Operations Inspection
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Sworn to and subscribed before
me this 12th day of June, 1980


Notary Public