November 25, 1979 and Dates of Initial Telephone November 26, 1979 Report Date: June 16, 1980 Occurrence: Time of Written July 29, 1980 Occurrence: 2316 to 0903 Report Date: DYSTER CREEK NUCLEAR GENERATING STATION FORKED RIVER, NEW JERSEY 08731 Non-Routine Environmental Operating Report Report No. 50-219/80-2 Exceeding a limiting condition as defined in the Environmental IDENTIFICATION Technical Specifications, Paragraph 2.1.4.2. when less than OF OCCURRENCE: two dilution pumps were operating for a period of 9 hours and 47 minutes, while the ambient water temperature was less than 60.0 F. This event was discovered during a routine inhouse Quality Assurance Audit held on June 12, 1980, and confirmed as a non-compliance by the plant staff on June 17, 1980. This event is considered to be a Non-Routine Environmental Operating Report as defined in the Technical Specifications, Appendix "B", Paragraph 5.6.2. Routine Shutdown Steady State Power CONDITIONS PRIOR Operation Hot Standby TO OCCURRENCE: Cold Shutdown Load Changes During Routine Power Operation Other (Specify) Refueling Shutdown X Routine Startup Operation 2.60 E 5 GPM Dilution Pump Flow: Circulation Water Pump 4.60 E 5 GPM Prior to the occurrence, the ambient water temperature in the intake canal was 56.1 F. The condenser discharge temperature and the US Route #9 discharge bridge temperature was 57.5 F and 58.8 F respectively.

DESCRIPTION OF OCCURRENCE:

A reactor scram occurred at 1703 on November 23, 1979. At the time of the scram the intake water temperature was 56.9 F and Dilution Pumps 1-1 and 1-2 were in operation. Both dilution pumps were shut down 127 minutes following the scram. Reactor startup commenced on November 25, 1979 with the reactor achieving criticality at 0553. Dilution Pump 1-1 had been started at 0056 the same date. At 2316 on November 25, 1979, the reactor mode switch was placed in the run mode at a power level of approximately 19 MW thermal. At 0903 on November 26, 1979, Dilution Pump 1-2 was started. During the operating

Non-Routine Environmental Operating Report Report No. 50-219/80-2

> period from 2316 on November 25, 1979, to 0903 on November 26, 1979, the intake temperature did not rise above 56.1 F. For 9 hours and 47 minutes, only one dilution pump was in operation while the intake water temperature was below 60.0 F.

APPARENT CAUSE OF OCCURRENCE:

X Procedure Design Unusual Service Condition Manufacture Inc. Environmental Installation/ Component Failure Construction Other (Specify) Operator

Plant procedures did not include provisions governing dilution pump operation during reactor startup.

ANALYSIS OF OCCURRENCE: Continuous operation of two dilution pumps when the intake water temperature is below 60.0 F during plant operation will reduce attraction of fish from accumulating and building up in the discharge canal. Proper pump operation will encourage fish to migrate south rather than remain in the discharge canal during the winter.

At the time the second dilution pump was started, the reactor power level was only 32% of rated power. The corresponding intake, discharge, and discharge bridge temperatures were 56.3 F, 61.6 F, and 61.1 F. Failure to operate the dilution pumps in accordance with Technical Specification 2.1.4.2 had minimal, if any, adverse biological effects on aquatic organisms.

CORRECTIVE ACTION:

Plant reactor startup procedures will be revised to incorporate criteria governing dilution pump operation as per Technical Specification, Appendix "B", Section 2.1.4.

FAILURE DATA:

Not Applicable.

Prepared by:

Date: 7 - 29 - 80

Approved by:

Date: 7-29-80