

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | Q | R | P | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | - | - | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

LICENSÉE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT

01 | R | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 0 | 7 | 2 | 8 | 8 | 0 | 0 | 8 | 0 | 4 | 1 | 8 | 0 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

02 | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
On 28 July, in Mode 5, while performing OP-401, Core Flooding System, check valve

03 | CFV-79 failed allowing approximately 500 gallons of liquid from the core flood

04 | system to enter the nitrogen system via NGV-4. The liquid backflowed through

05 | the nitrogen system into an unrestricted area and was released to the environment

06 | via relief valve NGV-215. There was no affect upon the general public as a re-

07 | sult of this event. This is the fourth occurrence of this type reported.

09 |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

SYSTEM CODE: S F (11) CAUSE CODE: E (12) CAUSE SUBCODE: B (13) COMPONENT CODE: V A L V E X (14) COMP SUBCODE: C (15) VALVE SUBCODE: A (16)

LER NO REPORT NUMBER: 80 (17) EVENT YEAR: 80 (18) SEQUENTIAL REPORT NO.: 027 (19) OCCURRENCE CODE: 01 (20) REPORT TYPE: T (21) REVISION NO.: 0 (22)

ACTION TAKEN: K (23) FUTURE ACTION: G (24) EFFECT ON PLANT: C (25) SHUTDOWN METHOD: Z (26) HOURS: 0000 (27) ATTACHMENT SUBMITTED: Y (28) NRC FORM 306: N (29) PRIME COMP SUPPLIER: X (30) COMPONENT MANUFACTURER: N425 (31)

10 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
The apparent cause of this event is attributed to the failure of core flood

11 | check valve, CFV-79, and the open position of low pressure nitrogen header

12 | isolation valve, NGV-4, which is normally locked closed. Immediate isolation

13 | was affected and decontamination of the spill area and affected piping started.

14 | CFV-79 failure evaluation will be conducted and appropriate Operating Procedures

15 | will be revised.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

FACILITY STATUS: G (32) POWER: 000 (33) OTHER STATUS: NA (34) METHOD OF DISCOVERY: A (35) DISCOVERY DESCRIPTION: Operator Observation (36)

16 | ACTIVITY RELEASED OR RELEASE: L (37) CONTENT: M (38) AMOUNT OF ACTIVITY: 1.0 millicuries (39) LOCATION OF RELEASE: Relief valve to environment (40)

17 | PERSONNEL EXPOSURES: NUMBER: 000 (41) TYPE: 4 (42) DESCRIPTION: NA (43)

18 | PERSONNEL INJURIES: NUMBER: 000 (44) DESCRIPTION: NA (45)

19 | LOSS OF OR DAMAGE TO FACILITY: TYPE: L (46) DESCRIPTION: NA (47)

20 | FACILITY: Y (48) DATE: 28 July 1980 (49) NRC USE ONLY

Name of preparer: E. K. Neuschaefer PHONE: (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

8008120380

SUPPLEMENTARY INFORMATION

Report No. 50-302/80-027/01T-0
Facility: Crystal River Unit #3
Report Date: 4 August 1980
Occurrence Date: 28 July 1980

Identification of Occurrence:

Uncontrolled release of radioactive liquid to the environment exceeding ten (10) times the maximum permissible concentration for Co-60 averaged over a twenty-four (24) hour period and a loss of one (1) day or more of the operation of the facility.

Conditions Prior to Occurrence:

Mode 5 cold shutdown.

Description of Occurrence:

While performing OP-401, Core Flooding System, for the purpose of bubbling nitrogen through Core Flood Tank "A" for mixing prior to sampling, Core Flood Check Valve CFV-79 failed, allowing approximately 500 gallons of liquid from the core flood tank to enter the nitrogen system via the low pressure nitrogen header isolation valve NGV-4. The liquid backflowed through the nitrogen system into an unrestricted area and was released to the environment via nitrogen relief valve, NGV-215. Analysis of the liquid released determined it to contain 1.42×10^{-2} $\mu\text{Ci/ml}$. Evaluations based on collected soil samples indicated that ≤ 20 gallons had been released, making the total activity released 1.07 μCi . Air samples taken immediately after discovery of the affected spill area indicated no airborne activity.

Designation of Apparent Cause:

The apparent cause of this event is attributed to the failure of Core Flood Check Valve CFV-79, and the open position of low pressure nitrogen header isolation valve, NGV-4, which is normally locked closed.

Analysis of Occurrence:

There was no affect upon the general public as a result of this event. The majority of the contamination has been cleaned up. Decontamination will continue until 10 CFR 20 limits have been met.

Corrective Action:

Perform decontamination of affected nitrogen system piping and localized spill area. Conduct a failure evaluation of core flood check valve CFV-79, and revise appropriate Operating Procedures to prevent recurrence of this type event.

Failure Data:

This is the fourth occurrence of this type reported; however, the first of this type involving a liquid release.