

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

① | M | A | Y | K | R | 1 | ② | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | ③ | 4 | 1 | 1 | 1 | 1 | ④ | _____ | ⑤
7 8 9 14 15 25 26 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T
① | L | ⑥ | 0 | 5 | 0 | 0 | 0 | 0 | 2 | 9 | ⑦ | 0 | 7 | 0 | 9 | 8 | 0 | ⑧ | 0 | 8 | 0 | 8 | 8 | 0 | ⑨
7 8 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

① | 0 | 2 | | During surveillance as part of IE Bulletin 79-17 Rev. 1 for stagnant bor
① | 0 | 3 | | ated lines leaks were found on both ends of CS-MOV-540. This degradation
① | 0 | 4 | | is required to be reported by T.S.6.9.4.b.4 and to perform the necessar
① | 0 | 5 | | y repairs both boron flow paths had to be isolated, of which at least on
① | 0 | 6 | | e is to be operable by T.S.3.1.2.2. This is the fourth flow path isolati
① | 0 | 7 | | on. In that leakage was minute and the unit has been in Mode 5 for 5 mon
① | 0 | 8 | | ths, there was no adverse effects upon the public health or safety. | 80

① | 0 | 9 | | R | B | ⑪ | B | ⑫ | C | ⑬ | P | I | P | E | X | X | ⑭ | B | ⑮ | Z | ⑯ |
9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
⑰ | 8 | 0 | | | 0 | 1 | 4 | | | 0 | 3 | | | 0 | |
21 22 23 24 26 27 28 29 30 31 32
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
⑱ | B | ⑲ | Z | ⑳ | Z | ㉑ | 0 | 0 | 0 | 0 | ㉒ | N | ㉓ | N | ㉔ | A | ㉕ | S | 4 | 2 | 0 | ㉖
33 34 35 36 37 40 41 42 43 44 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

① | 1 | 0 | | The root cause of this occurrence was weld defects during the original s
① | 1 | 1 | | ystem installation. The welds are on 4 inch, stainless steel, 150 psi de
① | 1 | 2 | | sign pressure pipe that is exposed to approximately 30-35 feet of water
① | 1 | 3 | | pressure. The welds were repaired and a successful liquid penetrant exam
① | 1 | 4 | | ination conducted. No further action is deemed necessary at this time. | 80

① | 1 | 5 | | G | ⑳ | 0 | 0 | 0 | ㉑ | N/A | ㉒ | D | ㉓ | Surveillance Per IE Bulletin 79-17 | 80
7 8 9 10 12 13 44 45 46
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

① | 1 | 6 | | Z | ㉔ | Z | ㉕ | N/A | ㉖ | N/A | ㉗ |
7 8 9 10 11 44 45
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

① | 1 | 7 | | 0 | 0 | 0 | ㉘ | N/A | ㉙ |
7 8 9 11 12 13
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

① | 1 | 8 | | 0 | 0 | 0 | ㉚ | N/A | ㉛ |
7 8 9 11 12
PERSONNEL INJURIES NUMBER DESCRIPTION

① | 1 | 9 | | Z | ㉜ | N/A | ㉝ |
7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

① | 2 | 0 | | N | ㉞ | 8008120 407 | N/A | _____ | 80
7 8 9 10 68 69
PUBLICITY ISSUED DESCRIPTION NRC USE ONLY

NAME OF PREPARER EDWIN L. MAY PHONE: (413) 625-6140