| CONTROL SLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)   |
|--|
| 0 1 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 56  |
| REPORT LG 0 5 0 0 0 3 2 7 7 0 7 1 1 8 0 8 0 8 0 8 8 0 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  Both ventilation chlorine detectors (0-CLAN-43-205 A and B) were found inoperable and             |
| [0]3]   the plant entered LCO 3.3.3.6. Deficiency was discovered during the performance of   |
| [0 4   SI-168. There was no danger to the health and safety of the public. Previous  |
| 0 5   occurrences - none.  |
| 06   |
| 07   |
| 7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE   |
| S G 1 E 12 E 13 I N S T R U 4 E 15 Z 16  |
| 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32  |
| ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER  E 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 L 25 W 0 2 5  CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) |
| [1] [As-found values for the chlorine detectors (model 50-125) did not meet Tech.Spec.   |
| requirements. The detectors were recalibrated and returned to service within one   |
| [1] [hour. The frequency of calibration is being temporarily changed to monthly to further   |
| [1] evaluate any drift problem. An optimum frequency of calibration will be determined from  |
| this data.   |
| TATILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32    B   (28)   O   O   O   (29) N/A   B   (31) Technician observation  |
| 7 8 Q 10 10 12 17 44 45 46 80  |
| TELEASED OF RELEASE OF AMOUNT OF ACTIVITY (3)  |
| PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 30  N/A  |
| 7 8 9 PERSONNEL INJURIES 13  |
| 18 0 0 0 0 (40) N/A  |
| LOSS OF OR DAMAGE TO FACILITY 43   |
| PUBLICITY ISSUED DESCRIPTION (45)  NRC USE ONL   |
| 12 0 N/A N/A 68 69   |
| 8008120734 Phone 615-842-0295  |