

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE							LICENSE NUMBER														LICENSE TYPE JO					57 CAT 58		

0	1	L	6	0	5	0	0	0	2	5	9	7	0	7	0	8	8	0	8	0	6	8	0	9
REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE							

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 1 With unit 1 at 93% steady state power, PCV 73-43 failed to operate properly during  
 0 2 HPCI SI 4.5.E.1.d and e. Redundant systems were proven operable. There was no  
 0 3 danger to the health or safety of the public, no significant resulting chain of  
 0 4 events, and no previous similar occurrences. See Technical Specification 3.5.E.2.  
 0 5  
 0 6  
 0 7

0	1	S	F	E	B	V	A	L	V	E	X	F	H		
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE	VALVE SUBCODE			
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION							
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
D		Z		Z		0000		Y		Y		L		L1170	

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 1 The valve was stuck closed due to the main valve guide becoming loose and unthreading.  
 1 2 The valve was disassembled and cleaned and the valve guide tightened. No recurrence  
 1 3 control is required due to no previous failure history.  
 1 4  
 1 5

1	1	E	0	9	3	NA	B	SI 4.5.E.1.d. and e.		
FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	Z	Z	NA	NA	NA	NA	NA		
ACTIVITY CONTENT		AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY ISSUED				
000		000		Z		N				

POOR ORIGINAL

NRC USE ONLY

NAME OF PREPARER \_\_\_\_\_ PHONE \_\_\_\_\_

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8055 Technical Specification Involved 3.5.E.2  
Reported Under Technical Specification 6.7.2.b (2)  
Date of Occurrence 7/8/80 Time of Occurrence 1630 Unit 1

Identification and Description of Occurrence:

While running SI 4.5.E.1.d and e on the HPCI, PCV-73-43 failed to operate properly.

Conditions Prior to Occurrence:

- Unit 1 - 93% steady state power.
- Unit 2 - 96% steady state power.
- Unit 3 - cold shutdown

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

CS, RHR, RCIC, and ADS logic proven operable.

Apparent Cause of Occurrence:

The valve was stuck closed due to the main valve guide becoming loose and unthreading.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no significant resulting chain of events, no release of activity, and no damage to plant or equipment.

Corrective Action:

The valve was disassembled and cleaned and the valve guide tightened. No recurrence control is required due to no previous failure history.

Failure Data:

NA

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 