

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. D. BOX 1640, JACKSON, MISSISSIPPI 39205

NUCLEAR PRODUCTION DEPARTMENT

August 1, 1980

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region I. 101 Maria ta Street, N.W. Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Dear Mr. O'Reilly:

80-266-000

THIS DOCUMENT CONTAINS POOR QUALITY PAGES

SUBJECT: Grand Gulf Nuclear Station

Units 1 and 2

Docket Nos. 50-416/417 PRD-80/25, 10CFR21 Report, Defective SB-12 Switches

AECM-80/173

References: 1) AECM-80/128, 6/12/80

2) AECM-80/152, 7/12/80

On July 10, 1980, Mississippi Power & Light Company sent your office a final report under 10CFR50.55(e) of a deficiency concerning GE Type SB-12 switches. We have since determined that this deficiency is applicable to 10CFR21. A supplemental report containing additional information to the report previously filed under 10CFR50. 55(e) is attached.

Yours truly,

J. P. McGaughy, Jr.

Assistant Vice President,

Nuclear Production

WDH:mt Attachment

cc: Mr. N. L. Stampley

Mr. R. B. McGehee

Mr. T. B. Conner

Mr. Victor Stello, Director

Division of Inspection & Enforcement U. S. Nuclear Regulatory Commission

Washingcon, D.C. 20555

1.	Identification of individual(s) informing the NRC:
	Name(s):
	T. E. Reaves
	Telephone call to Virgil Brownlee, NRC, Region II 8/1/80.
	Address: Mississippi Power & Light Company, P. O. Box 1640, Jackson, MS 39205
2.	Identification of entity failing to comply or containing a defect (check appropriate blocks):
	GRAND GULF NUCLEAR STATION
	Unit 1 X
	Unit 2
	Other _
	(Specify)
3.	Supplier: General Electric
	Switchgear Division Burlington, Iowa
	Durington, 10wa
	the country by
4.	Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply:
	See paragraph I & II of Attachment A to MP&L letter
	AECM-80/152 (attached)
5.	Date information obtained for this report: 8/1/80
6.	Additional information for defective components incorporated in other facilities, as applicable:
	Number in use, supplied for, or being supplied
	racility/bocación
	(Not known to MP&L)
7.	Corrective Action: See paragraph III of Attachment A to AECM-80/152 (attached)
	Responsibility: Mississippi Fower & Light Quality Assurance Section (Name of individual or organization)
	Time Required To Complete Action: Began 11/14/79; Complete at close of MCAR-GGNS #80 (estimate 9/80)
8.	Advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees:
	NRC IE Circular No. 79-17 was issued 8/11/79. Also, GE, Installation and
	Service Engineering Division forwarded Service Advice SED(073) No. 330.1
	to Bechtel Power Corporation. AE for GGNS. on 1/14/80.

	PUI EN LA	MI KEPUKE	AGLE DEFICIENCY (PRO) PRD # 80/26	
I	. DESCRIPTION: (Include none	conformanc	e document)	
	See Paragraph I, QA Form	16.20(A),	Rev. 3, attached.	
II.	. DETERMINATION OF EFFECT ON	SAFE OPER	ATION OR SUBSTANTIAL SAFETY HAZARD:	
	See Paragraph II, QA Form	16.20(A),	Rev. 3, attached	
	Could have adversely a or is a substantial sa	iffected the fety hazar	ne safe operation of the plant	
	Unable to determine wi	thin one v	orking day of receipt	
	Signature	I	Date Organization	
III.	. EVALUATION OF POTENTIAL REPORTABILITY:			
	Not Reportable			
	Reportable			
	Potentially Reportable			
	or Unable to Determine			
	Signature	Da	te Quality Assurance	
	See Paragraph II, QA Form	16.20(A),	Rev. 3, attached	
IV.	NOTIFICATION TO NRC:			
	Person Notified:		How Notification	
			Was Made:	
	Notified By:		Date:	
	See Paragraph III, QA Form			
V.	EVALUATION OF REPORTABILITY: Reportable Under10CFR50.55(e)10CFR21			
			10CFR21 Use Only-Senior Vice President	
			VI. RECEIPT OF INFORNATION: Date Time	
	SignatureD	ate	Signature	
VII.	REPORT TO NRC:	Due Date	6/11/80 7/10/80	
			l Date 6/12/80 7/10/80	
			umber _AECM-80/128	

POTENTIALLY REPORTABLE DEFICIENCY (PRD)

80/ PRD NUMBER 26

1. DESCRIPTION:

INP PA

As a result of investigation based on IE Circular 79/17, Bechtel has identified eight (8) switchgear units containing defective S5-12 switches. Each switchgear is furnished with two (2) SB-12 switches. The switches contain an intermittent contact problem which will cause a lack of continuity through the contact of the switch used to energize the trip coil of the circuit breaker. The switchgear units are used in the 6.9 KV system used for controlling the recirculating pumps.

	Initiated By: T. E. Reaves, Jr. Organization: MP&L Date: 5/12/80
II.	EVALUATION OF POTENTIAL REPORTABILITY:
	Rationale: Concurrence: Yes No Initial Date
	The potential exists that, should the condition remain uncorrected, it could Manager QA X WELLINGER 5/12/80 adversely affect the safety of operations of the Nuclear Power Plant.
	See Attachment "A" + Dir. of Pwr Prod
III.	NOTIFICATION TO NRC: Person Notified: M. Hunt How Notification Was Made: Telephone
	Notified By: A. Ramey Date: 5/12/80
IV.	EVALUATION OF REPORTIBILITY: Rationale: Concurrence: Yes No Initial Date
	Manager QA
	Project Mgr
	+ Dir. of Pwr Prod.
ν.	REPORT TO NRC: Due Date: 6/11/80
	Submitted Date:
10.5	Letter Number ;
VI.	CORRECTIVE ACTION VERIFICATION:
	By: Date:

⁺ Required should agreement not be reached between Mgr QA and Project Mgr.

Attachment "A" to PRD 80/26

The use of SB-12 switches in this particular application would have no adverse impact on plant safety since they are used in non-safety related switch gear. Therefore, this specific deficiency is not reportable under 10 CFR 50.55(e). However, since adverse impact may result from other applications, as yet unknown, this deficiency is considered to be potentially reportable and requires evaluation of its generic implications, if any.

W. E. Ege for T.E. Reaves

5/10/80



MISSISSIPPI POWER & LIGHT COMPANY

Kelping Build Mississippi P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

NUCLEAR PRODUCTION DEPARTMENT

July 10, 1980

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, N.W. Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Units 1 and 2 Docket Nos., 50-416/417 File 0260/15525/15526 PRD-80/26, Final Report, Defective SB-12 Switches (Ref.: AECH-80/ 128, June 12, 1980) AECM-80/152

On May 12, 1980, Mississippi Power & Light Company notified Mr. M. Hunt of your office of a Potentially Reportable Deficiency (PRD) at the Grand Gulf Nuclear Station (GGNS) construction site. The deficiency concerns CE Type S3-12 switches.

We have since determined this deficiency to be reportable within the meaning of IOCFR50.55(e). Details are described in the attached final report. We are evaluating the applicability of 10CFR21 and will submit a report upon completion.

Tours truly,

For J. P. McGaughy, Jr.

Assistant Vice President.

Nuclear Production

ATR:nt Attachment

cc: Mr. N. L. Stampley

Mr. R. B. McGehee

Mr. T. B. Conner

Mr. Victor Stello, Director

Division of Inspection & Enforcement U. S. Nuclear Regulatory Commission

Washington, D.C. 20555

bcc: Dr. D. C. Gibbs

Mr. J. P. McGaughy

Mr. J. N. Ward

Mr. A. Zaccarla

Mr. J. W. Yelverton

Mr. L. F. Dale

Mr. C. K. McCoy

Mr. T. H. Cloninger

Mr. R. A. Ambrosino

Mr. C. L. Tyrone PRD File

File

Dupe 8007170396

FINAL REPORT, PRD-80/26

I. Description of Deficiency

Defective SB-12 switches identified in IE Circular 79-17 were found to be installed in switchgear supplied by the vendor. The defect is an intermittent contact problem which will cause lack of continuity through the "a" contact of the switch that is used to energize the trip coil of the circuit breaker.

II. Safety Implications

The SB-12 switches are used in the circuit breakers of the 6.9 KV switchgear units which control the reactor recirculation pumps. The safety function of the breaker is to trip on a signal from the Reactor Protection System. The postulated failure of the SB-12 switch would prevent the energizing of the trip coil thereby preventing the breaker from fulfilling its intended safety function.

III. Corrective Action Taken

The vendor will furnish new SB-12 switches to correct the condition and preclude recurrence.

Dupe 8007170400

DUPLICATE DOCUMENT

Entire document previously entered into system under:

ANO 8007170400

No. of pages:

4