



ATTACHMENT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES CONTINUED

approximately 13 gpm. The valve stem was clamped closed to allow shutting off this high seal water supply and the remaining three RCP seal water supplies were adjusted to normal. There were no effects upon public health or safety because of this event.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS CONTINUED

this valve because of the high  $\Delta P$  and low throttling. Following this incident the plant was cooled down and all four of these hermetically sealed valves were replaced with the original style (Rockwell Fig. 3624-T, F-316, Class 1500 lb., 3/4") valve.

Rockwell International will perform detailed investigations into the cause of the failure. A follow-up report will be made upon receipt of further information from the valve vendor.