



Public Service Company of Colorado

16805 ROAD 19½
PLATTEVILLE, COLORADO 80651

August 11, 1980
Fort St. Vrain
Unit No. 1
P-80259

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Reference: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/80-40, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/80-40.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/cls

Enclosure

cc: Director, MIPC

A002
S
1/1

8008190 608

5

REPORT DATE: August 11, 1980

REPORTABLE OCCURRENCE 80-40

ISSUE 0

OCCURRENCE DATE: July 12, 1980

Page 1 of 2

FORT ST. VRAIN NUCLEAR GENERATING STATION
PUBLIC SERVICE COMPANY OF COLORADO
16805 WELD COUNTY ROAD 19 1/2
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/80-40/03-L-0

Final

IDENTIFICATION OF
OCCURRENCE:

On July 12, 1980, a sample required by SR NR 1.1 was not taken. This is being reported as a degraded mode of surveillance requirement NR 1.1 per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT
DESCRIPTION:

While operating at less than 2% power, the plant's semi-annual test of the auxiliary cooling method valves and equipment was being conducted on the day shift of July 12, 1980. This is a long and involved surveillance and it extended through the shift. The Operator assigned to collect the NR 1.1 sample was involved in switching electrical supplies to the various equipment and was unable to get to the sample point during the shift. Extra Operations personnel were on site to assist with the performance of the surveillance.

The samples prior to and after this missed sample were normal, and there is no indication that the chemistry changed during this period.

CAUSE
DESCRIPTION:

The sample was not taken because abnormal plant operations preempted the Operator's time.

CORRECTIVE
ACTION:

The sample was taken the next shift as required, and the surveillance was marked to indicate why the missing sample was not taken.

There was no affect on public health or safety.

No further corrective action is anticipated or required.

Prepared By: Asa B. Reed
Asa B. Reed
Technical Services Technician

Reviewed By: J. W. Gahn
J. W. Gahn
Technical Services Supervisor

Reviewed By: Frank M. Mathie
Frank M. Mathie
Operations Manager

Approved By: Don Warembourg
Don Warembourg
Manager, Nuclear Production