

NRC FORM 366  
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A R A N O 2 | 0 0 - 0 0 0 0 - 0 0 | 4 1 1 1 1 | \_\_\_\_\_  
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 CAT 56 5

CON'T  
 0 1 | REPORT SOURCE | L 0 5 0 0 0 3 | 6 8 7 0 1 6 0 3 8 0 | \_\_\_\_\_  
7 8 60 61 DOCKET NUMBER 68 80 EVENT DATE 74 75 REPORT DATE 80 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 0 2 | During Mode 1 operation, Safety Injection Tanks (SIT) "C" & "D" were  
 0 3 | found to have boron concentrations of 1711 ppm and 1620 ppm boron con-  
 0 4 | centration, which is below the 1731 ppm boron concentration as per  
 0 5 | T.S. 3.5.1.c. The SIT "A" & "B" boron concentrations were verified to  
 0 6 | be at acceptable levels. Prompt reportable per T.S.6.9.1.8.b due to  
 0 7 | simultaneous out of spec SIT's. No similar occurrences.

0 8 | \_\_\_\_\_  
7 8 9

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP SURCODE | VALVE SURCODE  
9 10 S I F 11 12 X 13 Z 14 Z Z Z Z Z Z 15 Z 16 Z  
17 LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.  
21 22 8 1 0 23 - 24 26 0 3 7 27 / 28 29 0 1 30 X 32 1  
 ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPD-4 FORM SUB | PRIME COMP SUPPLIER | COMPONENT MANUFACTURER  
33 34 E Z 35 Z 36 Z 37 40 0 0 0 0 41 42 Y 43 44 N 45 47 Z 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 1 0 | Cause of occurrence is believed to be dilution of the SIT makeup path by  
 1 1 | the reactor coolant during extended Shutdown Cooling System operation.  
 1 2 | This dilution, based on local sampling, may lower SIT boron concentration  
 1 3 | during makeup operation with the Refueling Water Tank as the source.

1 4 | \_\_\_\_\_  
7 8 9

1 5 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION  
7 8 9 1 10 11 1 0 0 12 13 NA 30 A 31 Monthly Sampling 32  
33 34 Z 35 Z NA 36 NA 37 NA

1 6 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE  
7 8 9 Z 10 11 Z NA 35 NA 36 NA

1 7 | PERSONNEL EXPOSURES | TYPE | DESCRIPTION  
7 8 9 0 0 0 37 Z 38 NA 39

1 8 | PERSONNEL INJURIES | DESCRIPTION  
7 8 9 0 0 0 40 NA 41

1 9 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION  
7 8 9 Z 42 NA 43

2 0 | PUBLICITY ISSUED | DESCRIPTION  
7 8 9 N 44 NA 45

NAME OF PREPARER: Chris N. Shively  
 PHONE: 501/968-2519  
 8009030425

1. Reportable Occurrence Report No. 50-368/80-037

2. Report Date:

3. Occurrence Date: 6/3/80

4. Facility: Arkansas Nuclear One - Unit II  
Russellville, Arkansas

5. Identification of Occurrence:

Operation of the Emergency Core Cooling System with the Safety Injection Tanks (SIT) operability less conservative than the least conservative aspect of the limiting condition for operation defined in T.S. 3.5.1.c.

6. Conditions Prior to Occurrence:

Steady-State Power	<u>  X  </u>	Reactor Power	<u>  2815  </u> MWth
Hot Standby	<u>          </u>	Net Output	<u>  =925  </u> MWe
Cold Shutdown	<u>          </u>	Percent of Full Power	<u>  100  </u> %
Refueling Shutdown	<u>          </u>	Load Changes During Routine Power Operation	<u>          </u>
Routine Startup Operation	<u>          </u>		
Routine Shutdown Operation	<u>          </u>		
Other (specify)			

7. Description of Occurrence:

Two SIT's boron concentration simultaneously out of specification for less than one hour.

During routine sampling of the SIT's, it was discovered that SIT "C" and "D" had boron concentrations less than 1731 ppm boron specified in T.S. 3.5.1.c. SIT "A" and "B" boron concentrations were verified to be greater than 1731 ppm boron.

Reportable Occurrence Report No.

8. Designation of Apparent Cause of Occurrence:

Design	_____	Procedure	_____
Manufacture	_____	Unusual Service Condition Including Environmental	_____
Installation/ Construction	_____	Component Failure (See Failure Data)	_____
Operator	_____		
Other (specify)	Boration path dilution		

Based on local sampling tests, a portion of the SIT fill path may be diluted (from the RWT concentration) by reactor coolant during extend Shutdown Cooling System operation. With such dilution occurring during the small makeup operations, the SIT boron concentration is decreased.

9. Analysis of Occurrence:

The SIT's require periodic makeup to maintain T.S. required levels due to volume contraction during unit cooldowns and volume reductions during normal operation.

Reportable Occurrence Report No.

10. Corrective Action:

The SIT fill path and fill method is being evaluated to ensure undiluted boration. Boron stratification in the SIT is also being studied. SIT "C" and "D" were returned to the Tech Spec required boron concentrations utilizing the feed-and-bleed method.

11. Failure Data:

There have been no similar occurrences.

11. Failure Data: