NRC FO	U.S. NUCLEAR REGULATORY COMMISSION UPDATED REPORT - PREVIOUS REPORT DATE 041080 LICENSEE EVENT REPORT
•	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 B	N E C P R 1 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T	SOURCE LL 6 0 15 10 10 10 12 19 18 7 10 13 1 1 2 8 0 3 10 18 12 0 18 10 9 10 10 10 10 10 10 10 10 10 10 10 10 10
0 2	During a scheduled inspection of the RCIC turbine, it was discovered that two buc-
0 3	kets on the turbine wheel were damaged. This could have resulted in operation in a
0 4	degraded mode as permitted by Tech. Spec. Section 3.5.D. The reactor was in cold
0 5	shutdown condition at the time of the occurrence and RCIC was not required to be op-
0 6	prable by the Tech. Specs. The RCIC system had met the Tech. Spec. surveillance re-
0 7	quirements at the time the reactor was shutdown and was considered operable. There
0 8	were no adverse affects to the public health and safety.
09	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 24 26 27 28 29 30 31 32 24 26 27 28 29 30 30 31 32 24 26 27 28 29 30 30 31 32 32 32 32 32 32 32 32 32 32 32 32 32
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	Investigation indicates the RCIC turbine wheel was damaged by non-impact type im-
111	pingement of a foreign object on the wheel. The object could not be located. The
TIE	Terry wheel (Terry Turbine Part No. 77595A-24) was replaced. No further action is
13	planned.
7 8	3
1 5	THE STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA
117	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA
	9 PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41 NA
T O	LZ 42 NA
20	PUBLICITY SOURCE DESCRIPTION 45 NRC USE ONLY NRC USE ONLY
	NAME OF PREPARER Richard D. Flannigan PHONE 402-825-3811
8009050/90	