LICENSEE EVENT REPORT

	EIGENSEE EVENT HEFORT
	CONTROL BLOCK:
0 1	N E C P R 1 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 58
ON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 9 8 7 0 7 1 3 8 0 8 1 1 8 0 9
0 2	During normal operation, while increasing power, the G.E. Reactor Vent Monitor,
0 3	
04	significant event took place except for the vent monitor alarm. A redundant system
0 5	which continuously monitors was available and was operable at the time of the occur-
0 6	rence. No adverse consequences from the standpoint of public health and safety
0 7	bccurred.
0 8	
8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE
0 9	BB B (1) E (12) LG (13) LT N S T R U (14) P (15) LZ (16)
	SEQUENTIAL OCCURRENCE REPORT TYPE NO. 17 REPORT 8 0 0 1 0 1 0 1 1 0 0
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER MANUFACTURER ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. 5 PLIER METHOD FORM SUB. 5 PLIER METH
	33 34 35 36 37 40 41 42 43 44 47 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The cause of the power supply failure was two failed capacitors. The capacitors
	are of the electrolytic type which degrade in time. New capacitors were installed
112	and the unit placed back into service. The capacitors were Cl and C2 on Drawing
1 3	117C2684 for G.E. Area Radiation Monitor Power Supply. The other channels corres-
14	ponding capacitors will be checked during the next surveillance test.
1 5	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIP
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA NA
7 8	9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 10 10 10 1371 7 1(38)
7 8	9 11 12 13 80 PERSONNEL INJURIES 80
	O TO TO TO THE NA DESCRIPTION (41) NA DESCRIPTION (41) NA DESCRIPTION (41) NA DESCRIPTION (41)
1 5	TYPE DESCRIPTION NA
7 B	PUBLICITY (ID) NRC USE ONLY
20	LN 40 NA
8	NAME OF PREPARER Jerry L. Scheer PHONE 402-825-3811 8
090	NAME OF PREPARER