

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

MAY 1 3 1980

In Reply Refer '.'o: RII: JPO 50-325 50-324

> Carolina Power and Light Company Attn: J. A. Jones Senior Executive Vice President and Chief Operating Officer 411 Fayetteville Street Raleigh, NC 27602

Gentlemen:

Enclosed is IE Bulletin No. 80-07, Supplement No. 1, which specifies the NRC offices that should receive written reports submitted in response to this Bulletin.

Should you have any questions regarding this Bulletin or the actions required by you, please contact this office.

Sincerely,

James P. O'Reilly

Director

Enclosures: 1. IE Bulletin No. 80-07, Supplement No. 1 2. List of IE Bulletins

Recently Issued

8009090 055

Carolina Power and Light Company

•

.

۰.

.

may

-2-

cc w/encl: A. C. Tollison, Jr. Plant Manager Box 458 Southport, North Carolina 28461

SSINS No.: 6820 Accession No.: 8005050055

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

May 13, 1980

PLICATE

IE Bulletin No. 80-07 Supplement No. 1

BWR JET PUMP ASSEMBLY FAILURE

C. Reporting Requirements

The information in Items A.3, and B.1, is requested under the provisions of 10 CFR 50.54(f). Accordingly, you are requested to provide within the time periods specified in these items, written statements of this information, signed under oath or affirmation.

These reports should be submitted to the Director of the appropriate NRC Regional Office and a copy should be forwarded to the NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection, Washington, D.C. 20555.

Approved by GAO, B180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

IE Bulletin No. 80-07 Supplement No. 1

14

Enclosure May 13, 1980

RECENTLY ISSUED IE BULLETINS

| Bulletin No. | Subject | Date Issued | Issued To |
|-------------------|---|-------------|---|
| 80-07 Suppl. 1 | BWR Jet Pump Assembly Failure | 5/13/80 | All GE BWR-3 & BWR-4 reactor facilities with an OL |
| 80-13 | Cracking In Core Spray Spargers | 5/12/80 | All BWR's with an OL |
| 80-12 | Decay Heat Removal System Operability | 5/9/80 | Each PWR with an GL |
| 80~11 | Masonry Wall Design | 5/8/80 | All power reactor facilities with an OL, except Trojan |
| 80-10 | Contamination of Nonradioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment | 5/6/80 | All power reactor facilities with an OL or CP |
| 80-09 | Hydramotor Actuator Deficiencies | 4/17/80 | All power reactor operating facilities and holders of power reactor construction permits |
| 80-08 | Examination of Containment Liner Penetration Welds | 4/7/80 | All power reactors with a CP and/or OL no later than April 7, 1980 |
| 80-07 | BWR Jet Pump Assembly Failure | 4/4/80 | All GE BWR-3 and BWR-4 facilities with an OL |
| 80-0ti | Engineered Safety Feature (ESF) Reset Controls | 3/13/80 | All power reactor facilities with an OL |
| 80-05 | Vacuum Condition Resulting In Damage To Chemical Volume Control System (CVCS) Holdup Tanks | 3/10/80 | All PWR power reactor facilities holding OLs and to those with a CP |
| 79-01B | Environmental Qualification of Class IE Equipment | 2/29/80 | All power reactor facilities with an OL |
| 80-04 | Analysis of a PWR Main Steam Line Brea. With Continued Feedwater Addition | 2/8/80 | All PWR reactor facilities holding OLs and to those nearing licensing |