



TIC

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

May 13, 1980


Docket No. 50-245

Northeast Nuclear Energy Company  
ATTN: Mr. W. G. Council  
Vice President - Nuclear  
Engineering and Operations  
P. O. Box 270  
Hartford, Connecticut 06101

Gentlemen:

The enclosed IE Bulletin No. 80-07, Supplement No. 1, "BWR Jet Pump Assembly Failure," is forwarded to you for action. A written response is required. This Supplement specifies the NRC offices that should receive written reports submitted in response to this Bulletin. If you desire additional information regarding this matter, please contact this office.

Sincerely,

  
for Boyce H. Grier  
Director

Enclosures:

1. IE Bulletin No. 80-07, Supplement No. 1
2. List of Recently Issued IE Bulletins

CONTACT: D. L. Capton  
(215-337-5254)

cc w/encls:

J. F. Opeka, Station Superintendent  
D. G. Diedrick, Manager of Quality Assurance  
J. R. Himmelwright, Licensing Safeguards Engineer

8009090 |||

ENCLOSURE 1

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS No.: 6820

Accession No.:

8005050055

*dup*

IE Bulletin No. 80-07

Supplement No. 1

Date: May 13, 1980

Page 1 of 1

BWR JET PUMP ASSEMBLY FAILURE

C. Reporting Requirements

The information in Items A.3, and B.1, is requested under the provisions of 10 CFR 50.54(f). Accordingly, you are requested to provide within the time periods specified in these items, written statements of this information, signed under oath or affirmation.

These reports should be submitted to the Director of the appropriate NRC Regional Office and a copy should be forwarded to the NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection, Washington, D.C. 20555.

Approved by GAO, B180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

ENCLOSURE 2

IE Bulletin No. 80-07  
Supplement No. 1  
Date: May 13, 1980  
Page 1 of 1

RECENTLY ISSUED IE BULLETINS

| Bulletin No. | Subject   | Date Issued | Issued To  |
|--------------|---|-------------|--|
| 80-06        | Engineered Safety Feature (ESF) Reset Controls  | 3/13/80     | All Power Reactor Facilities with an Operating License (OL) (For Action)<br>All Power Reactor Facilities with a Construction Permit (CP) (For Information) |
| 79-03A       | Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe   | 4/4/80      | All Power Reactor Facilities with an OL or CP  |
| 80-07        | BWR Jet Pump Assembly Failure   | 4/4/80      | BWR 3 & 4's with OL (For Action)<br>BWR's with CP (For Information)  |
| 80-08        | Examination of Containment Liner Penetration Welds  | 4/7/80      | All Power Reactor Facilities with an OL or CP  |
| 80-09        | Hydromotor Actuator Deficiencies  | 4/17/80     | All Power Reactor Facilities with an OL or CP  |
| 80-10        | Contamination of Nonradioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment | 5/6/80      | All Power Reactors with OL (for action)<br>with CP (for information)   |
| 80-11        | Masonry Wall Design   | 5/8/80      | All Power Reactor Facilities with an OL, Except Salem 2  |
| 80-12        | Decay Heat Removal System Operability   | 5/9/80      | All PWRs with an OL  |
| 80-13        | Cracking in Core Spray Spargers   | 5/12/80     | All BWRs with an OL  |