

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 GA E I H 1 2 000-000000-000 3 4 1 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 5R

CON'T
01 REPORT SOURCE L 6 0500000321 7 081580 8 090480 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While the reactor was operating at 2370 MWT the reactor building vent
03 radiation monitor sample pump failed. Attempts to start the backup sam-
04 ple pump also failed. Work was initiated to get a pump operable. The
05 Lab was notified to take daily samples as per Tech Specs. There were no
06 effects upon public health and safety due to this event. This is a re-
07 petitive occurrence and was last reported on LER 50-321/1980-072.

08 _____ 80

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
M C E B P O M P X X H Z
9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 0 0 9 7 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
B Z Z Z 0000 Y Y N G 0 4 6
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event has been attributed to moisture swelling the
11 carbon vanes in the pump thus locking the pump so it was unable to move.
12 In order to prevent a recurrence, these pumps will be rotated on a daily
13 basis. Also a quarterly preventative maintenance program will be estab-
14 lished for these pumps.

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 099 N/A Z N/A
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z N/A N/A
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
000 Z N/A
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION
000 N/A
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z N/A
7 8 9 10 80

20 PUBLICITY ISSUED DESCRIPTION
N N/A
7 8 9 10 80

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

NARRATIVE REPORT

Reportable Occurrence Report No. 50-321/1980-97

With the reactor in the run mode at 2370 MWT, the operator noticed a Hi-Low Flow Alarm for the Reactor Building Vent Sample System. Laboratory personnel were sent to investigate. The sample pump had failed, and the lab personnel noted that there was a blown fuse for the pumps. The fuse was replaced and the pump failed to start. Another fuse was inserted and the back up pump was switched on but failed to start.

A maintenance request was initiated and given to a maintenance foreman to repair the pumps.

The cause of the back up pump not operating has been determined to be swelled carbon vanes. This was probably caused by moisture. In order to prevent a recurrence, the pumps will be rotated on a daily basis. A quarterly preventative maintenance program will also be established for these pumps.

There were no Technical Specifications violated and the pump was operating within 12 hours of the time the alarm was noticed by the operator. This type of pump is used in the Main Stack and Recombiner Building Off Gas Sample System. The pumps in the Main Stack had a history of similar failures.

There were no effects upon safe plant operation or upon public health or safety.