LICENSEE EVENT REPORT

| | CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
|-------|--|
| 0 1 | N E C P R 1 2 0 0 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 |
| CON'T | REPORT L 6 0 5 0 0 0 2 9 8 7 0 8 2 8 8 0 8 0 9 0 9 0 8 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) |
| 0 2 | During routine surveillance testing, PC-232MV, drywell supply inboard isolation valve |
| 0 3 | failed in mid-position. This event is repetitive (ref. LER 79-39). The outboard |
| 0 4 | isolation valve was operable so that containment isolation could be attained. In |
| 0 5 | addition, PC-232MV can be manually positioned. There were no adverse effects on |
| 0 6 | public health and safety. |
| 0 7 | |
| 0 8 | J 90 |
| 0 9 | SYSTEM CODE CODE SUBCODE SUBCO |
| | COMPONENT COMP |
| 10 | The operator for PC-232MV is a Limitorque SMB-00. The operator contact cam was found |
| 11 | broken where it was pinned to the drive shaft. The cam was replaced with an ident- |
| 1 2 | ical part. The damaged cam has been returned to Limitorque for analysis. This is |
| 113 | an interim report; an updated report will be issued when the analysis is complete. |
| 1 4 | |
| 1 5 | ACILITY DISCOVERY DESCRIPTION 32 LE 28 10 9 9 29 NA B 31 Operator Observation |
| | LEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA |
| 1 7 | NUMBER TYPE DESCRIPTION 39 NA |
| 1 D | PERSONNEL INJURIES NUMBER O O O O NA NA |
| 1 9 | USS OF OH DAMAGE TO FACILITY (43) TYPE DESCRIPTION Z (42) NA |
| 2 0 | PIGRE GATY SUED DESCRIPTION (45) N (44) NA 1 1 1 1 1 1 1 1 1 1 |
| 010 | 070298 68 69 80.5 |