

FGE



August 7, 1980
CPY-771-80

Mr. R. H. Engelken, Director
Nuclear Regulatory Commission, Region V
1990 North California Blvd.
Walnut Creek, California 94596

Dear Sir:

In accordance with the Trojan Plant Operating License, Appendix A, US NRC Technical Specifications, Paragraph 3.4.10.3, attached is Licensee Event Report No. 80-14, concerning a situation where a seismic restraint was installed in an incorrect location on the service water supply line to a train "A" ESF cooler.

Sincerely,

C. P. Vandt
C. P. Vandt
General Manager

JCP
CPY/JCP:na
Attachments

c: LER Distribution List

8008150388

S

A002
111
80-194

REPORTABLE OCCURRENCE

1. Report No.: 80-14
2. a. Report Date: August 7, 1980
b. Occurrence Date: July 9, 1980
3. Facility: Trojan Nuclear Plant, PO Box 439, Rainier, Oregon 97048

4. Identification of Occurrence:

A seismic restraint was found to be installed in an incorrect location on the 1-1/2-inch service water supply line to the train "A" control room emergency ventilation system cooling coil.

5. Conditions Prior to Occurrence:

The plant has been in all operational modes including at 100% of rated power while the restraint was in the incorrect location.

6. Description of Occurrence:

During a field verification of as-built information, a seismic restraint was found to be installed at an incorrect location on the 1-1/2-inch service water supply line to the train "A" control room emergency ventilation system cooling coil. The restraint was installed improperly during construction of the plant.

7. Designation of Apparent Cause of Occurrence:

The cause of this occurrence was construction personnel error.

8. Analysis of Occurrence:

This occurrence had no effect on either plant or public safety. The train "B" cooling oil was operable and available for use.

9. Corrective Action:

The restraint was removed and reinstalled in the proper location.