LICENSEE EVENT REPORT
CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1   M   D   C   C   N   1   2   0   0   -   0   0   0   -   0   0   3   4   1   1   1   1   4   57 CAT 58   5
O 1 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
O 2 LAt 1230 the containment Radiation Monitoring System (RMS) pump failed resulting
0]3 [in a loss of the containment gaseous and particulate radiation monitors
0 4 1 (T.S. 3.4.6.1). The redundant RMS pump was started and the gaseous and
O[5] [particulate monitors were returned to service at 1245. The containment
o 6 [monitors were returned to service at 1245. The containment level alarm system
o 7   remained operable during the event. LER's 79-52 (U-1) and 79-22 (U-2)
ols [describe similar events.
SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
17   REPORT   18   0   0   4   6   0   0   0   0   0   0   0   0   0
The affected sampling pump was removed from service. A spare pump was installed.
[1] [Plant maintenance will be investigating and repairing the pump. When the cause
[1] Lof the failure is determined a follow-up report will be submitted.
13
7 8 9
FACILITY STATUS  TO BE 28 ON 81 9 29 NA  METHOD OF DISCOVERY DESCRIPTION 32  NA OPERATOR OF DISCOVERY DESCRIPTION 32
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
7 8 9 SESSON 11 12 13 DESCRIPTION (39) NA
NUMBER DESCRIPTION 41) NA
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA  NA  NA
PUBLICITY   SSUED   DESCRIPTION (45)   NA   NA   NA   NA   NA   NA   NA   N
0 00 99 90 370