

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 M D C C N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T

0 1 L 6 0 5 0 0 0 3 1 7 7 0 9 0 3 8 0 8 0 9 1 7 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | During normal operation, #12 Control Room Air Conditioner was stopped for

0 3 | maintenance and #11 was started. Twelve minutes later it was discovered

0 4 | that the compressor for #11 unit was not running. Two minutes later, it was

0 5 | discovered that the compressor had tripped on overload. The overload was

0 6 | reset at that time and the unit then started. Momentarily, both units had been

0 7 | inoperable, which is a violation of T.S. 3.7.6.1. LER 80-38 (U-1) describes

0 8 | a similar event.

0 9 S G 11 E 12 A 13 C K T B K R 14 I 15 Z 16

17 LER/RO REPORT NUMBER 8 9 0 4 8 0 1 T 0

ACTION TAKEN A 18 G 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 7 0 0 0 0 0 N 23 Y 24 A 25 C 7 7 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | A faulty reset switch on the overload for #11 A/C compressor was found during

1 1 | investigation. The reset switch was replaced. Plant procedures are being

1 2 | revised to require an operability check of the idle Control Room Air

1 3 | Conditioner when securing the operating unit.

1 4 |

1 5 E 28 1 0 0 0 29 NA A 31 Operator Observation 32

1 6 Z 33 Z 34 NA NA 36

1 7 0 0 0 37 Z 38 NA 39

1 8 0 0 0 40 NA 41

1 9 Z 42 NA 43

2 0 Z 44 NA 45

NAME OF PREPARER R. L. Wenderlich/W. B. Pence

PHONE: (301)269-4776/4815

8009230592