

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

<u>10/1/</u>	<u>V/A/N/A/S/1/</u> (2)	<u>3/0/-/0/0/0/0/0/-/0/0/</u> (3)	<u>4/1/1/1/1</u> (4)	<u>/ / /</u> (5)
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT

REPORT SOURCE	/L/ (6)	/0/5/0/0/0/3/3/8/ (7)	/0/9/0/4/8/0/ (8)	/0/9/0/4/8/0/ (9)
	DOCKET NUMBER	EVENT DATE	REPORT DATE	

SECRET NUMBER	EVENT
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)	

10/2/ / On September 4, 1980, while operating in Mode 1 at 100% power, sample analysis /

/0/3/ / of SI accumulator 1B revealed the boron concentration to be 2109 ppm, exceeding/

/0/4/ / T.S. 3.5.1 which stipulates that the concentration be maintained between 1900 /

10/5/ / and 2100 ppm. Since the boron concentration was brought back within the spec-/

/0/6/ / ification in 2½ hours, the health and safety of the public were not affected. /

10/7/ /

10/8/ /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMP. SUBCODE	VALVE SUBCODE
----------------	---------------	------------------	------------------	------------------

<u>/O/9/</u>	<u>/S/F/</u> (11)	<u>/X/</u> (12)	<u>/Z/</u> (13)	<u>/A/C/C/U/M/U/</u> (14)	<u>/Z/</u> (15)	<u>/Z/</u> (16)
			SEQUENTIAL	OCCURRENCE	REPORT	REVISION
LER/RO	EVENT	YEAR	REPORT NO.	CODE	TYPE	NO.

(17)	REPORT NUMBER	18/0/	1-/	107/5/	1 \ /	10/3/	1L/	1-/	10/
------	------------------	-------	-----	--------	-------	-------	-----	-----	-----

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
-----------------	------------------	--------------------	--------------------	-------	-------------------------	---------------------	-------------------------	---------------------------

(26) /X/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /Y/ (23) /N/ (24) /N/ (25) /D/1/0/0/

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The high sample concentration is believed to have been caused by stratifica- /

/1/1/ / tion of the stagnant solution in the accumulator. Corrective action was /

/1/2/ / to partially drain 1B accumulator and replenish it from #1 RWST to achieve the /

/1/3/ / proper concentration.

/1/4/ /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/E/ (28)	/1/0/0/ (29)	/ NA / (30)	/B/ (31)	/ROUTINE SAMPLE

[illegible]

RELEASED	OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)

<u>1/6/</u>	<u>1/2/</u> (33)	<u>1/2/</u> (34)	/	NA	/	/	NA	/
-------------	------------------	------------------	---	----	---	---	----	---

PERSONNEL EXPOSURES		
NUMBER	TYPE	DESCRIPTION (39)

/1/7/ /0/0/0/ (37) /Z/ (38) / NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

1/8/ 10/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION	(15)
(1) (2)	(3) (4)	(5)

1/9/ 7/ (42) NA

[illegible]

ISSUED	DESCRIPTION (45)	NRC USE ONLY
12/01	IN/ (46) NA	/ / / / / / / / / / / / / /

2/0/ N/ (44) NA

NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151

8009230615

Virginia Electric and Power Company
North Anna Power Station, Unit 1
Docker No. 50-338
Report No. LER 80-075/03L-0

Attachment: Page 1 of 1

Description of Event

On September 4, 1980 while operating in Mode 1 at 100% power, sample analysis of SI accumulator 1B revealed the boron concentration to be 2109 ppm, exceeding T.S. 3.5.1 which stipulates the concentration be maintained between 1900 and 2100 ppm.

Probable Consequences of Occurrence

Since the boron concentration was brought back within specification in 2½ hours, the health and safety of the public were not affected.

Cause of Event

The high sample concentration is believed to have been caused by stratification of stagnant boric acid in the accumulator.

Immediate Corrective Action

Corrective action was to partially drain 1B accumulator and replenish it from the RWST to achieve the proper boron concentration.

Scheduled Corrective Action

No scheduled corrective action is required.

Actions Taken to Prevent Reccurrence

No action is required.

Generic Implications

Stratification of boric acid in stagnant tanks is a generic problem.