

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALB R F 1 2 0 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T  
01 REPORT SOURCE L 6 C 5 0 0 0 0 2 5 9 7 0 8 2 0 8 0 8 0 9 1 6 8 0 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation while performing SI 4.8.B.4-2, CAM-1-RM-90-251 for the turbine  
03 building roof vent was removed from service for a period exceeding one hour.  
04 (TS 4.8.B.1.a). A redundant system was operable. There was no hazard to the public  
05 health or safety. Previous events: 259/7432, 259/795, 259/796, 259/7924, 259/8032,  
06 259/8038, and 260/7820.  
07  
08  
09

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
B B 11 E 12 B 13 P U M P X X 14 X 15 Z 16  
9 10 11 12 13 14 15 16 17 18 19 20  
17 LLR/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 0 0 6 3 0 3 L 0  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
C 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 N 25 N 3 0 5 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTION (27)

10 A Schwitzer Series 325 Model 145473 vacuum pump failed resulting in the unit  
11 being out of service longer than normal. Chemical laboratory was notified to take  
12 samples. Personnel have been cautioned to be more attentive to the period of time  
13 the CAM is out of service. The vacuum pump was replaced.  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
E 28 0 9 6 29 NA B 31 Routine testing  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF A /ITY LOCATION OF RELEASE  
Z 33 Z 34 NA NA  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 NA  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 NA  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 NA  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

20 PHYSICALLY INJURED DESCRIPTION  
N 44 NA  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER

PHONE

8009230 714

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8063 Technical Specification Involved 4.8.B.1.a

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 8/20/80 Time of Occurrence 0853 Unit 1

Identification and Description of Occurrence:

While performing SI 4.8.B.4.2, CAM 1-RM-90-251 for the turbine building vent was removed from service for a period exceeding one hour.

Conditions Prior to Occurrence:

U-1 at 96% MWe.

U-2 at 93% MWe

U-3 at 100% MWe

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Chemical Laboratory notified to take samples.

Apparent Cause of Occurrence:

Vacuum pump failure.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no damage to the plant equipment, and no resulting significant chain of events.

Corrective Action:

The vacuum pump was replaced. Personnel were cautioned to be more attentive to the time limit that the equipment can be out of service.

Failure Data:

259/7432, 259/795, 259/796, 259/7924, 259/8032 and 260/7820.

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 