LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M N P 1 N 2 0 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT 58
CON'T O 1 REPORT 1 O O O O O O O O O
0 2 With Unit 1 in refueling shutdown, ultrasonic examination of steam generator support
[0]3 bolts revealed that most of the bolts had crack indications. Several bolts failed
0 4 when detensioning was attempted. Unit 2 was operating at 100% power when the discovery
[0] [was made. Unit 2 was shut down the evening of 9-4-80 to perform similar inspections.]
Unit 2 bolts were found pre-tensioned and 3 of the total of 48 were found cracked.
0 7 Remaining Unit 2 bolts were detensioned and inspected. All support pads were
Old provide with at least 5 bolts which is sufficient for LOCA plus DBE loading.
SYSTEM CAUSE CODE SUBCODE SUBC
LER/RO EVENT YEAR REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PHIME COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER ACTION AND CORRECTIVE ACTIONS 27
Four Vascomax 250 CVM bolt heads and one complete bolt were forwarded to Westinghouse
Research and Development Center for analysis. Preliminary analysis indicates
[1]2 [environmentally assisted cracking. The cracks can be prevented by a reduction in
installation torque. All Unit 1 bolts will be replaced and installed with a
minimum of pre-tension. A followup report will be submitted.
FACILITY STATUS TO THER STATUS TO THER STATUS TO DISCOVERY DESCRIPTION (3.) TO B 9 10 12 13 44 45 46 DISCOVERY DESCRIPTION (3.)
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 5 Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 8 9 11 12 13 PERSONNEL INJURIES 13 80
NUMPER DESCRIPTION (41) NA NA NA
LOSS OF OR DA 'AZE TO FACILITY (43)
7 8 9 10 NA NRC USE ONLY
SSUED DESCRIPTION OF NA I I I I I I I I I I I I I I I I I I
8009230741 PHONE: