LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 :	
CON'T	SOURCE LLG 015 10 10 10 12 9 15 7 0 6 1 19 8 10 8 0 9 2 2 8 10 0
0 2	During normal operation, operating personnel noted that Loop D overpower/
0 3	overtemp. delta T channel 1T-431 became erratic in nature initiating
0 4	Lassociated alarms and bistable trips. This condition was nonconservative
0 5	for overpower and overtemp. delta T Rx. trips and Hi Stm Line flow with
0 6	Low-Low Tary Safety Injection and Steam Line Isolation. Since the re-
0 7	dundant channels were operable, the health and safety of the public
0 8	was not affected.
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17 REPORT 18 0
10	The cause of the erratic behavior was due to a noisy output from the low
111	level amplifier 1TM431B (Hagan Model #18). Blown capacitor C38 and 8
1 2	defective 68/69 date code capacitors were found and replaced within the
1 3	module. The channel returned to service. Since this type of failure
14	has not been a recurring problem no further action is required.
7 .8	PACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 33 0 9 8 29 NA A 31 Operator Observation 30 30 30 30 30 30 30 3
1 6	ACTIVITY CONTENT PELEASED OF RELEASE AMOUNT OF ACTIVITY 35 2 33 2 23 NA
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
1 18	NUMBER O O O O O NA NA 80
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA BOOK
2 0	ISSUED DESCRIPTION (5) 8010020 484
7 8	NA 6010020 407