

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 9 6 7 0 9 0 9 8 0 8 0 9 3 0 8 0 9
7 8 9 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while performing SI 4.7.H, H₂M-76-39 would not calibrate.

0 3 (T.S. 3.7.H). Redundant H₂E-76-37 was operable. There was no hazard to the

0 4 public health or safety. Previous event: 50-260/8036.

0 5

0 6

0 7

0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SURCODE VALVE SUBCODE
S E 11 E 12 E 13 I N S T R U 14 E 15 Z 16
7 8 9 10 11 12 13 14 15 16

17 LER III REPORT NUMBER 8 0 21 22
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
X 18 F 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 N 25 G 0 8 0
11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Sensor type 47E226428G2, instrument H₂E 76-39 failed. The redundant sensor

1 1 H₂E-67-39A was placed in service and the SI successfully completed. The system

1 2 will be changed out with a new designed system.

1 3

1 4

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 0 7 6 NA B 31 Surveillance Testing
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY NUMBER DESCRIPTION NRC USE ONLY
N 44 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER

8010060314

PHONE

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 8037 Technical Specification Involved 3.7.H

Reported Under Technical Specification 6.7.2.b (2)

Date of Occurrence 9/9/80 Time of Occurrence 1300 Unit 3

Identification and Description of Occurrence:

H₂M-76-39 would not calibrate to specification.

Conditions Prior to Occurrence:

U-1 at 96% MWe

U-2 at 0% MWe

U-3 at 76% MWe

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

H₂E-76-39 hydrogen sensor failed.

Analysis of Occurrence:

There was no damage to the plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health and safety of the public.

Corrective Action:

The hydrogen analyzing system will be changed to a new designed system at the next refueling outage.

Failure Data:

260/8036, 259/7930, 260/7923, 296/796, 259/7815 and 260/7821.

*Retention: Period - Lifetime: Responsibility - Administrative Supervisor

*Revision: 