_	LICENSFE EVENT REPORT
•	CONTROL BLOCK:
0 1	M D C C 1 1 2 2 0 0 0 - 10 0 0 0 - 10 0 3 3 1 1 1 1 1 1 4 57 CAT 58 5
CON'T	SOURCE 50 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9
0 2	During normal operation, 228 Safety Injection Tank (SIT) level indica-
03	tion became erratic and increased to >199" at 0320. The reactor was
04	placed in Mode 3 and pressure reduced <1750 psig per T.S. 3.5.1.b at
0 5	1425. The level transmitter was replaced and recalibrated. Estimated
05	tank level prior to draining was 246". 228 SIT was returned to ser-
07	vice at 0245 on 9/15/80. The three other SIT's remained operable dur-
7 8	ing this event. This event is similar to LER 80-50 (Docket #05000317).
0 9 7 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LERIRO EVENT YEAR REPORT NO.
10	No cause has been determined for the erratic tank level indication.
	Bench tests performed on the replaced transmitter have revealed no
112	malfunction. Neither sense line nor isolation valve leakage was ob-
13	served during replacement of the transmitter and calibrations performed
7 8	in the field.
1 5	FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 C 28 0 4 0 29 NA 44 45 46 46 46 46
	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) IZ 33 Z 34 NA SERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) NA NA SERSONNEL EXPOSURES
1 7	NUMBER TYPE DESCRIPTION (39) NA 9 PERSONNEL INJURIES 13 80
1 8	NUMBER DESCRIPTION (41) NO 10 10 10 10 10 11 12 Loss OF OR DAMAGE TO FACILITY (43)
19	Z 42 DESCRIPTION NA
20	PUBLICITY ISSUED DESCRIPTION 45 IIA IIA RRC USE ONLY STATE OF THE PROPERTY
	NAME OF PREPARER J.S. Lagiewski/P.G. Rizzo PHONE (301) 269-4747/4736

LER NO. 80-43/3L DOCKET NO. 50-38 EVENT DATE 09/14/80 ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

During the next Unit 2 Refueling Outage additional work is to be performed on the process sensing lines to the transmitter. Connecting fittings will be replaced and additional testing for leaks will be performed under Maintenance Request 0-80-2940.