* :	*1	14.	3	Ann	200
		77			

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 4 L B R F 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T O 1 SOURCE 60 O 5 0 0 0 2 6 0 7 1 0 0 5 8 0 8 1 0 2 1 8 0 9 SOURCE 60 O 61 DOCKET NUMBER 68 O 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2 During fuel-shuffling operations, fuel was placed in cell 58-19 with adjacent
[0]3] control rod, 54-19, withdrawn. There was no fuel in cell 54-19. There was no
previous occurrences. There was no hazard to public health or safety. See
technical specification 3.10.A.2
06
07
08 60
SYSTEM CAUSE CODE SUBCODE SUBC
TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 20 ATTACHMENT NORD-4 PRIME COMP.
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The procedure for fuel support casting replacement was deficient due to a lack of
precautions and holdpoints. Control rod 54-19 was inserted and refuel interlocks placed
in service. Procedure will be revised to correct deficiencies.
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA A (31) Operator observation
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA NA
7 8 9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
PEHSONNEL INJURIES NUMBER DESCRIPTION 41
LOSS OF OR DANGE TO FACILITY (43)
TYPE DESCRIPTION I D
PUBLICITY 155U-10 DESCRIPTION 45 TVA media information telephone
7 8 9 10

8010270491

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8041 Technical Specification Involved 3.10.A.2
Reported Under Technical Specification 6.7.2.a (6)
Date of Occurrence 10/5/80 Time of Occurrence 1530 Unit 2
Identification and Description of Occurrence: Placed fuel in cell 58-19 with adjacent control rod, 54-19, withdrawn. There was no fuel in cell 54-19.
Conditions Prior to Occurrence:
Unit 2 @ refueling
Unit 3 @ 1025 MWe.
Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.
NA
Apparent Cause of Occurrence:

Procedure error.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

The fuel support casting replacement procedure will be revised to assure all refueling interlocks normal after maintenance.

Failure Data:

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: