

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

OCT 2 1980

In Reply Refer To: RII:JP0 50-395

> South Carolina Electric and Gas Company ATTN: T. C. Nichols, Jr., Vice President Power Production and Systems Operations P. O. Box 764 Columbia, SC 29218

Gentlemen:

The enclosed IE Circular No. 80-22, is forwarded to you for information. No written response is required. Should you have any questions related to your understanding of the recommendations on this matter, please contact this office.

Sincerely,

James P. O'Reill∛ Director

Enclosures:

- 1. IE Circular No. 80-22
- 2. List of Recently Issued IE Circulars

cc w/encl:

- A. A. Smith, Site QA Coordinator
- T. B. Conners, Jr.
- O. S. Bradham, Manager Nuclear Operations

8010270 568

SSINS: 6830 Accession No.: 8006190055

UPE

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

October 2, 1980

IE Circular No. 80-22: CONFIRMATION OF EMPLOYEE QUALIFICATIONS

In recent months, the Nuclear Regulatory Commission has determined that in two unrelated actions a utility and an architect-engineering company employed technically unqualified individuals as designers/engineers by failing to confirm the validity of their technical and educational qualifications as presented in their employment applications. In both of these instances, the employers mistakenly assumed that the personnel firms supplying these individuals had investigated fied persons in both of these cases were discovered as a result of allegations to this effect, rather than through internal company procedures, we believe that this matter warrants your attention.

We are hereby recommending that your employment procedures be reviewed to determine that your company has in effect employment policies which confirm the professional qualifications of employees. In the event you conclude that your present procedures do not fully address this matter, we recommend that you take prompt remedial action in this regard.

No written response to this Circular is required. If you desire additional information regarding this subject, contact the Director of the appropriate NRC Regional Office.

IEC 80-22 October 2, 1980

RECENTLY ISSUED IE CIRCULARS

| Circular | | Date of | |
|----------|--|---------|--|
| No. | Subject | Issue | Issued to |
| 80-22 | Confirmation of Employee Qualifications | 10/2/80 | All holders of a power reactor OL or CP |
| 80-21 | Regulation of refueling crews | 9/10/80 | All holders of a power reactor OL or CH |
| 80-20 | Changes in Safe-Slab Tank Dimensions | 8/21/80 | All Part 50 and Part 70 fuel facility licensees |
| 80-19 | Noncompliance with License Requirements for Medical Licensees | 8/26/80 | All medical licensees |
| 80-18 | 10 CFR 50.59 Safety Evaluations for Changes to Radioactive Waste Treatment Systems | 8/22/80 | All power reactor facilities with an OL or CP |
| 80-17 | Fuel Pin Damage Due to Water Jet from Baffle Plate Corner | 7/23/80 | All holders of PWR OLs and PWR CPs |
| 80-16 | Operational Deficiencies In Rosemount Model 510DU Trip Units And Model 1152 Pressure Transmitters | 6/27/80 | All power reactor facilities with an OL or a CP |
| 80-15 | Loss of Reactor Coolant Pump Cooling and Natural Circula- tion Cooldown | 6/20/80 | All power reactor facilities with an OL or CP |
| 80-14 | Radioactive Contamination of Plant Demineralized Water System and Resultant Internal Contamination of Personnel | 6/24/80 | All holders of power and research reactor licenses (operating and construction permits), and fuel cycle licensees |
| 80-13 | Grid Strap Damage in Westinghouse Fuel Assemblies | 5/18/80 | All holders of reactor OLs and CPs |
| 80-12 | Valve-Shaft-To-Actuator Key May Fall Out of Place When Mounted Below Horizontal Axis | 5/14/80 | All holders of reactor OLs and CPs |

4