

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C | A | H | M | B | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T 01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 1 | 3 | 3 | 7 | 0 | 9 | 2 | 6 | 8 | 0 | 8 | 1 | 0 | 2 | 6 | 8 | 0 | 9

02 | With the nuclear plant shutdown, a leak was observed in the housing of the gate valve at the #6 screen wash pump discharge. The housing had a 1-1/2" hole through it. The #6 pump is one of 2 pumps (with 4 backups) that provide shutdown heat removal for the reactor. This is reportable under T.S. IX.I.2.b.(2). There were no adverse effects; alternate sources were available even though not needed due to the length of the current shutdown (4 yrs.). Reference LER 80-005-03L-0.

09 | SYSTEM CODE: W B 11; CAUSE CODE: E 12; CAUSE SUBCODE: D 13; COMPONENT CODE: V A L V E X 14; COMP. SUBCODE: E 15; VALVE SUBCODE: D 16; LER/RO REPORT NUMBER: 80 17; SEQUENTIAL REPORT NO.: 006 24; OCCURRENCE CODE: 03 28; REPORT TYPE: L 30; REVISION NO.: 0 32; ACTION TAKEN: C 18; FUTURE ACTION: Z 19; EFFECT ON PLANT: Z 20; SHUTDOWN METHOD: Z 21; HOURS: 0000 22; ATTACHMENT SUBMITTED: N 23; NPRD-4 FORM SUB.: N 24; PRIME COMP. SUPPLIER: A 25; COMPONENT MANUFACTURER: W 0 3 0 26

10 | Failure was due to corrosion and erosion, a natural end of life. The valve is to be replaced by a Pratt monoflange MK II butterfly valve.

15 | FACILITY STATUS: G 28; % POWER: 000 29; OTHER STATUS: N/A 30; METHOD OF DISCOVERY: A 31; DISCOVERY DESCRIPTION: OPERATOR OBSERVATION 32

16 | ACTIVITY CONTENT RELEASED: Z 33; AMOUNT OF ACTIVITY: N/A 34; LOCATION OF RELEASE: N/A 35

17 | PERSONNEL EXPOSURES: NUMBER: 000 37; TYPE: Z 38; DESCRIPTION: N/A 39

18 | PERSONNEL INJURIES: NUMBER: 000 40; DESCRIPTION: N/A 41

19 | LOSS OF OR DAMAGE TO FACILITY: TYPE: Z 42; DESCRIPTION: N/A 43

20 | PUBLICITY: ISSUED: N 44; DESCRIPTION: N/A 45

NAME OF PREPARER: P. W. Baum

PHONE: 707/443-2787

8010280467

NRC USE ONLY