LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) J(1)CONTROL BLOCK: G A E I H 2 0 0 - 0 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 1 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 3 0 1 LICENSE NUMBER LICENSEE CODE 110 L 6 0 5 0 0 0 3 6 6 7 0 9 2 9 8 0 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 REPORT 8 0 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) With the plant shutdown and performing HNP-2-3309, High Pressure Coolant 0 2 Injection Turbine Exhaust Diaphragm Pressure Functional Test and Calibra-03 tion, 2041-NO12D HPCI Turbine Exhaust Diaphragm pressure switch actuated 04 at 11.8 psig. Tech Spec table 3.3.2-2 requires actuation at ≤10 psig. Re-0 5 dundant switches 2E41-NO12A, B and C were within tolerance. Public health 0 6 and safety was not affected. Plant operation was not affected. This is a 0 7 repetitive event as last reported on Reportable Occurrence 50-366/1980-020. 0 8 80 8 9 SYSTEM COMP VALVE CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE CODE [Z] (16) 10 (14) 5 (15) II IR IN IS I | B | (11 Z (13) XI (12) 0 9 19 REVISION REPORT SEQUENTIAL OCCURRENCE REPORT NO. CODE TYPE NO. EVENT YEAR LER/RO 0 013 13 17 L (17)REPORT 8 0 NUMBER 20 COMPONENT NPRD-4 PRIME COMP. SUBMITTED ACTION FUTURE TAKEN ACTION SHUTDOWN METHOD HOURS (22) MANUFACTURER FORM SUB. SUPPLIER B 0 6 9 Y 3 0 0 0 N (24) N (25) (21) 0 L (18) Z CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of this event has been attributed to setpoint drift. The 10 switch was immediately recalibrated as per HNP-2-5279, Barksdale 1 1 Pressure Switch Calibration, and functionally tested successfully. No further reporting is required. 4 80 9 METHOD OF DISCOVERY FACILITY (30)DISCOVERY DESCRIPTION (32) OTHER STATUS % POWER B (31) Surveillance 0 0 0 NA G (28) 80 45 CONTENT ACTIVITY LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE NA NA Z (33) Z (34) 6 45 80 4.5 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE NA 0 0 0 37 Z 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 0 0 (40) NA 80 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION NA 7. (42) 80 PUBLICITY NRC USE ONLY DESCRIPTION (45) ISSUED N (44) NA 68 69 80 8 0102 80476 REPARER R. T. Nix, Supt. of Maint. 912-367-7781 PHONE ..

L.R No.: 50-366/1980-137 Licensee: Georgia Power Company Facility Name: Edwin I. Hatch Docket No.: 50-366

Narrative Report for LER 50-366/1980-137.

On September 29, 1930, while the reactor was shutdown and while performing HNP-2-3309, HPCI Turbine Exhaust Diaphragm Pressure Functional Test and Calibration, pressure switch 2E41-N012D was found actuating at 11.8 psig. Tech Spec Table 3.3.2-2 requires actuation at ≤10 psig. Pedundant switches 2E41-N012A, B and C were operable and in tolerance. Public health and safety was not affected by this event. Plant operation was not affected by this event. This event was repetitive as last reported on Reportable Occurrence Report 50-366/1980-02[.

The cause of this event has been attributed to setpoint drift. The switch, Barksdale Model D2H, was immediately recalibrated as per HNP-2-5279, Barksdale Pressure Switch Calibration, and functionally tested successfully and returned to service. The unit is now in full compliance and no further reporting is required.

A generic review of this event revealed no inherent problems. Unit I does not use the same type switch for this application.