


YANKEE ATOMIC ELECTRIC COMPANY



ROWE, MASSACHUSETTS 01367

March 27, 1973



peguiator

United States Atomic Energy Commission Washington, D. C. 20545

Attention: Directorate of Licensing Reference: License No. DPR-3 (Docket 50-29)

Dear Sirs:

In accordance with Section D (1) (b) of the plant license we are reporting the following variance in the pressurizer code safety valve set pressures.

The pressurizer safety values are provided to prevent system pressure from exceeding design limits. The two pressurizer code safety values are Dresser 2" x 3" Model 1719 WA values with a capacity of 92,000 pounds/hour/value. The safety value designations and set points are:

PR-SV-181	2485 psig	
PR-SV-182	2560 psig	

These safety values are removed and tested on a test stand with nitrogen at refueling intervals for pressure settings and spring load data. Both have had a past history of conformance with the ASME Code requirements. However during the Core 9-10 refueling in March 1972, the "as found" set point pressures were out of tolerance.

> PR-SV-181 Was 175 pounds above the code set point limit. PR-SV-182 Was 174 pounds above the code set point limit.

The valves were disassembled and thoroughly inspected. No abnormal conditions were noted during this inspection. The valves were reset on the test stand to the correct set points.

These same safety values were removed and retested in November 1972 under the direction of a Dresser Industries representative. Again a variance was noted in the "as found" pressure set points with both values lifting above the required settings.

The Dresser representative disassembled and inspected both safety valves. The spindles were found to be bent between .012" - .014". Subsequent investigation by the service engineer concluded that one phase of the existing test procedure could have a detrimental effect on the valve spindles. In his opinion, measuring the safety valve spring loading during deflection could result in spindle distortion. This test was "smally performed with the valve fully assembled, and warned of possible spring tension loss.

8010310 691

2100

. The pressurizer safety valve test procedure was revised to eliminate this problem. Subsequent tests confirmed repeated lifts within code tolerances.

The pressurizer code safety valves will be removed and retested during the next major plant outage. This time interval to be no earlier than six months and no later than the Core 10-11 refueling outage. The valve vendor will be consulted before and during this next test.

A safety evaluation has been completed of the effects of the 175 psi overpressure on system component and transient conditions. The evaluation indicates that no system or transient safety problem would have resulted if the overpressure condition had occurred.

Very truly yours,

Herbert a. antis

Herbert A. Autio Plant Superintendent

HAA

meg

cc: J. O'Reilly

· .		(TEMPORAR	RY FORM	()	R	COM	TROL NO	: 2100.		
		104000 000 000				FIL	7			
FROM:		DATE OF DOC:	DAT	E REC'D	LTR	MEHO	RPT	OTHER		
Yankee Atomic E	Lectric Compan	4								
Rowe, Massachuse		3-27-73	2.1	30-73	x	1.000				
Herbert A. Autio	5	ORIG			1 ^					
		Unio	cc	OTHER	1		EC FDR			
DL		3 signed	1.0	1.200		SENT I	LOCAL P	DR		
CLASS: (UPROP)	N70	INPUT	NO CY	S REC'D		DAGIES	1.110			
			1.0 01	S ALC D		DOCIET	: 20:			
				ho	1	-	20			
DESCRIPTION:			ENCLO	SURES:		50-2	29			
Ltr reporting an v code.safety valve										
NOTE: *PLEASE CIRC					5					
RECEIVED FO	OR FULL DISTRI	BUTION			Do	Not Re	movo			
					Entre:	10.111.000	nove			
PLANT NAMES: Yanke	0	2도 같은 것 같아.			AUN	1017F	ICCU.			
							Wind			
		FOR ACTION/IN	FORMA	NOIS	3-31	-73	AR			
BUTLER(L) SCH	HWENCER(L)	ZIEMANN(L)		A Residue And and a first of the standard	BLOOD (I	and the sub-spectrum sector sector	<u> </u>			
	Copies	W/ Copies			opies	-)				
	DLZ(L)	ROUSE(FM)		REGAN						
V/ Copies W/	Copies	W/ Copies			opies					
	SSALLO(L)	DICKER(E)			oprop					
	Copies	W/ Copies	5	W/ C	opies	1.00	1.0			
	HEAL(L)	KNIGHTON(E	E)							
W/ Copies W/	7 Copies	W/ Copies	3	W/ C	opies					
and the second sec		INTERNAL DIST	RIBUTI	ON						
EG FILE	TECH REVIEW	DENTON		F & M		WAD	E	E		
EC PDR	HENDRIE	GRIMES		SMILEY		BRO	WN	E		
GC, ROOM P-506A	SCHROEDER	GAMMILL		NUSSBAUM	ER	G.	WILLIAN	SE		
	MACCARY *	KASTNER				SHE	PPARD	E		
	KNIGHT(2)	BALLARD		LIC ASST				1.1		
	PAWLICKI	SPANGLER		SERVICE	L		IND			
OYD . MOORE-L(ERR)	SEAO			WILSON	L		ITMAN			
EYOUNG-L(PAR)	STELLO * HOUSTON	ENVIRO		GOULBOUR		SAL	TZMAN			
	NOVACK	MULLER		SMITH	L					
. COLLINS	ROSS	DICKER		GEARIN	L	PLA				
	IPPOLITO	KNIGHTON YOUNGBLOOD		DIGGS	L		ONALD			
	TEDESCO *	REGAN		TEETS LEE	L	DUB	E			
TILE & REGION(2)	LONG	FROJ LEADE		MAIGRET	L	TATE	~			
And some from the set	LAINAS	FROD LEADE		SHAFER	L	INF	MILES.			
	BEMAROYA	HARLESS	-	DIATER .	r oc 14		MI LED.			
	VOLLMER									
*0.017 000		EXTERNAL DIST	RIBUTI	ON						
-LOCAL PDR -DTIE(ABERNATEY)										
-NSIC(BUCHAMAN)	(1)(2)(9)-NATION					R-SAN/I			
-ASLB-YORE/SAIRE			1-R. CARROLL- C, GT-B227					1- GERALD LELLOUCHE		
WOODWARD/H ST.			1- R. CATLIN, E-256-GT					BROOKHAVEN NAT. LAB		
-CYS ACPS HELEDING S	ETT TO LTC ACC	1- CONSU					1-AGMED (WALTER KOEST			
	TEETS ON 4-2			JME/AGABI			-427, (
1 10/100 82/1	1 1 4=C	- (D) I= GERLA	DULRI	KSON	JENL.	1 - E	D. MTT	LER F-3		
門開風	7個相平臣	11				7- 1				

ATA BTO

-

4

Yajkee Atomic Electric Company

- 3 -

AUG 3 0 1977

cc: Mr. Donald G. Allen, President Yankee Atomic Electric Company 20 Turnpike Road Westboro, Massachusetts 01581

> Greenfield Public Library 402 Main Street Greenfield, Massachusetts 01581