

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 7 8 V Y V T S 1 14 2 0 0 - 0 0 0 0 0 - 0 0 25 3 4 1 1 1 1 30 4 57 CAT 58 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0 1 7 8 REPORT SOURCE 60 61 L 6 0 5 0 0 0 2 7 1 68 7 0 9 2 9 8 0 74 8 1 0 2 9 8 0 80 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing a Two Rod Interlock Functional Test on rod 38-35, the position switch

0 3 | and rod block associated with the "one control rod withdrawal permit circuit" was

0 4 | found to be inoperable. T. S. 3.12.A.1 requires the control rod block interlock to be

0 5 | operable while in the Refuel Mode and performing core alterations. Control rod 38-35

0 6 | was returned to position 00 and electrically disarmed. There were no potential

0 7 | consequences to the health and safety of the public. A similar event was reported

0 8 | as RO 76-18.

7 8 9 80

0	9	SYSTEM CODE I E (11)		CAUSE CODE E (12)	CAUSE SUBCODE E (13)	COMPONENT CODE I N S T R U (14)				COMP. SUBCODE S (15)	VALVE SUBCODE Z (16)	
7	8											
(17) LER/RO REPORT NUMBER		EVENT YEAR 8 0 (21) (22)			SEQUENTIAL REPORT NO. 0 3 0 (24) (25) (26)			OCCURRENCE CODE 0 3 (28) (29)		REPORT TYPE L (30)		REVISION NO. 0 (32)
ACTION TAKEN A (18)	FUTURE ACTION Z (19)	EFFECT ON PLANT Z (20)	SHUTDOWN METHOD Z (21)	HOURS 0 0 0 0 (22) (23) (24) (25)				ATTACHMENT SUBMITTED H (23)	NPRD-4 FORM SUB. N (24)	PRIME COMP. SUPPLIER N (25)	COMPONENT MANUFACTURER G 0 8 0 (26) (27) (28) (29)	
33	34	35	36	37				41	42	43	44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 An investigation has shown that the position indicating switch on rod 38-35 at the

1 1 Full-in interlock position was stuck and remained stuck following rod withdrawal

1 2 to notch position 02. This provided a false "All Rods In" signal to the Reactor

1 3 Manual Control System. The defective switch was replaced by replacing control rod

1 4 38-35 Position Information Probe.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	H	28	0	0	0	29	NA	30
7	8	9	10	11	12	13	14	15	16
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40		41	NA	42
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42		43	NA	44	NA	45
7	8	9	10	11	12	13	14	15	16
PUBLCITY ISSUED		DESCRIPTION							
2	0	N	44		45	NA	46	NA	47
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER Warren P. Murphy

PHONE: (802) 257-7711